



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 MITSUBISHI XPANDER

GLX MID | 111,682 KM

VIN: MK2K6T1Y8NN001490

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	111682	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	MK2K6T1Y8NN001490		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Running Lights	
Rear Bumper Spoiler			
 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	



Safety & Security

Parking Sensors Rear



Reverse Camera



Airbag Driver Front



Airbag Passenger Front



Entertainment

Bluetooth Player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door
Panel: Paint Defect



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel
Condition: Low Visual Dent



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top	✓	
Alloy Wheel/ Rim		
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim
Rim: Alloy Edge Scuffing		✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim
		✓
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance
		✓
Engine Oil (Condition & Level)	✓	Exhaust System
		✓
Radiator Condition	✓	Radiator Coolant
		✓
Transmission Operation		
Gear Shifting	✓	Drive Axle
		✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder
		✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Infotainment Display
		✓
Music System	✓	Camera
		✓

Lights

Headlight



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Scuffing/
Disfiguration/ Melted > 80 mm



Central Console



Steering Wheel

Color Faded



Headliner



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE