



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 JAC JS4

INTELLIGENT | 81,848 KM

VIN: LJ12EKS37P4723422

Car highlights



Boosted Engine

This car has a Boosted Engine



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	81848	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	LJ12EKS37P4723422		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Parking Sensors Rear	
Reverse Camera		Front Camera	
Side Camera		Airbag Sides	
Airbag Driver Front		Airbag Passenger Front	
ABS			



Comfort & Convenience

Climate Control AC



Cruise Control



Power Window front -
Drivers Side



Power Window front -
Passenger Side



Power Windows Rear



Exteriors

Roof Rails



Running Lights



Rear Bumper Spoiler



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
------------------	---	----------------	---

Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off > 5mm			
--	---	--	--

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Scuffing/ Scratch, Low Visual Dent	
--------------------	---	--	---

Rear Bumper Condition

Rear Bumper			
-------------	---	--	--

Hood Condition

Hood Bonnet: Acid Marks/ Bird Dropping < 5mm			
---	---	--	--

Roof Condition

Roof			
------	---	--	--

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass			
----------------	---	--	--

Windshield Condition

Front Windshield		Rear Windshield	
------------------	---	-----------------	---

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys	
Master Key	✓

Dashboard

Instrument Panel



Controls



Infotainment Display



Music System



Camera



Lights

Headlight

Left: Light Scuff Marks < 50mm



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Steering Wheel

Steering Wheel Fair Use Wear



Headliner



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<73%

LHS Rear Tyre

<73%

RHS Front Tyre

<73%

RHS Rear Tyre

<73%

Spare Tyre

<35%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE