



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MG 5

STD | 77,137 KM

VIN: LSJA36E39RZ031594

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 77137             |  Specs             | Yes                   |
|  Engine           | 1.5L              |  Option Type       | Basic                 |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 14.9 km/L mileage     |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color Silver |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags             |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys                |
|  VIN number     | LSJA36E39RZ031594 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                   |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                                       |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                                  |  | Power Windows Rear                |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                   |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                    |  |
| Airbag Driver Front                                                                                                  |  | Airbag Passenger Front            |  |

|                                                                                                        |   |              |
|--------------------------------------------------------------------------------------------------------|---|--------------|
| ABS                                                                                                    | ✓ |              |
|  <b>Exteriors</b>     |   |              |
| Running Lights                                                                                         | ✓ |              |
|  <b>Entertainment</b> |   |              |
| Bluetooth Player                                                                                       | ✓ | Apple Play ✓ |
| Android Auto Play                                                                                      | ✓ |              |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Light Scuffing < 50mm



Rear left door



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper



### Hood Condition

Hood



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board

Condition: Light Scuffing < 80mm



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |
| Music System     | ✓ | Camera               | ✓ |
| Lights           |   |                      |   |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ | AC System Leaks    | ✓ |
| Power/ Manual Windows   | ✓ |                    |   |



## Interiors & Luggage

|                                |   |                                                |   |
|--------------------------------|---|------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel<br>Steering Wheel Fair Use Wear | ! |
| Headliner                      | ✓ | Toolkit                                        | ✓ |



## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <45% | LHS Rear Tyre             | <65% |
| RHS Front Tyre             | <45% | RHS Rear Tyre             | <65% |
| Spare Tyre                 | <55% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE