



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 TOYOTA RUSH

GX | 86,362 KM

Car highlights



Great condition

Car has low imperfections



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat

Basic Details

| | | | |
|--|--------------------------|---|-----------------------------|
|  Kilometers | 86362 |  Specs | Yes |
|  Engine | 1.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV | Fuel Efficiency | 14.0 km/L mileage |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 7 Seats |  Number of keys | 2 Keys |
|  VIN number | MHKEF8CFXLK002324 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|-----------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side |  | Power Windows Rear |  |
|  Exteriors | | | |
| Fog Light Front |  | Roof Rails |  |
| Rear Bumper Spoiler |  | | |



Safety & Security

Parking Sensors Rear



Reverse Camera



Airbag Sides



Airbag Curtain Shield



Airbag Driver Front



Airbag Passenger Front



ABS



Entertainment

Bluetooth Player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front right door

Panel: Low Visibility Dent < 30mm



Rear left door

Panel: Colour faded



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Grill Condition



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



Steering, Suspension & Brakes

Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Fair Use Wear



Dashboard

Instrument Panel



Controls



Infotainment Display



Music System



Camera



Lights

Headlight



Tail Light Cluster



| | | | |
|-------------------------|---|-----------------|---|
| Daylight Running Lights | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC System Leaks | ✓ |
| Power/ Manual Windows | ✓ | | |

Interiors & Luggage

| | | | |
|--------------------------------|---|----------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel | ✓ |
| Headliner | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <73% | LHS Rear Tyre | <73% |
| RHS Front Tyre | <73% | RHS Rear Tyre | <73% |
| Spare Tyre | <35% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE