



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 TOYOTA YARIS

E | 62,403 KM

VIN: MR2BF9C38P0037575

## Car highlights



### **Great condition**

Car has low imperfections



### **Great Parking Assistance**

Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 62403             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 17.5 km/L mileage    |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MR2BF9C38P0037575 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Safety &amp; Security</b>     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Airbag Driver Front                 |  |
| Airbag Passenger Front                                                                                               |  | ABS                                 |  |
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

|                 |                                                                                   |
|-----------------|-----------------------------------------------------------------------------------|
| Rear right door |  |
|-----------------|-----------------------------------------------------------------------------------|

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Colour Mismatch/ Low Brightness 

### Hood Condition

#### Hood

Bonnet: Paint Damage/ Low Brightness 

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|            |                                                                                     |                    |                                                                                       |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|
| Boot Floor |  | Firewall Condition |  |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Head Light Support Condition |  |
|------------------------------|-------------------------------------------------------------------------------------|

### Cowl Top

|          |                                                                                     |
|----------|-------------------------------------------------------------------------------------|
| Cowl Top |  |
|----------|-------------------------------------------------------------------------------------|

### Alloy Wheel/ Rim

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ✓ |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |
| Music System     | ✓ |                      |   |
| Lights           |   |                      |   |

|                  |   |                    |   |
|------------------|---|--------------------|---|
| Headlight        | ✓ | Tail Light Cluster | ✓ |
| Air Conditioning |   |                    |   |
| AC Cooling       | ✓ | AC System Leaks    | ✓ |


**Interiors & Luggage**

|                                |   |                               |   |
|--------------------------------|---|-------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Steering Wheel<br>Color Faded | ! |
| Headliner                      | ✓ | Toolkit                       | ✓ |


**Tyres**

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <55% |
| RHS Front Tyre             | <55% | RHS Rear Tyre             | <55% |
| Spare Tyre                 | <55% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE