



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 MG GT

LUXURY | 49,958 KM

VIN: LSJA36U92RN083159

Car highlights



Great condition

Car has low imperfections



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	49958	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Yellow
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LSJA36U92RN083159		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control 		360 degree Camera 	
Lane Departure Warning System 		Parking Sensors Rear 	
Reverse Camera 		Front Camera 	
Side Camera 		Airbag Sides 	
Airbag Curtain Shield 		Airbag Driver Front 	

Airbag Passenger Front	✓	ABS	✓
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Power Window front - Drivers Side	✓	Power Window front - Passenger Side	✓
Power Windows Rear	✓		
 Performance			
Paddle Shift	✓		
 Exteriors			
Running Lights	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Turbocharger/ Supercharger	✓	Radiator Condition ✓
Radiator Coolant	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Infotainment Display ✓
Music System	✓	Camera ✓
Lights		

Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<85%
RHS Front Tyre	<45%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE