



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 MITSUBISHI ATTRAGE**

**GLX HIGHLINE | 89,822 KM**

VIN: MMDAFT6J0NH008274

## **Car highlights**



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 89822             |  Specs             | Yes                   |
|  Engine           | 1.2L              |  Option Type       | Fully Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 20.2 km/L mileage     |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Maroon |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags             |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys                |
|  VIN number      | MMDAFT6J0NH008274 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                          |  |                                                                                                |                                   |                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|-----------------------------------|--------------------------------------------------------------------------------------------------|
| <div> Exteriors</div>                 |  |                                                                                                |                                   |                                                                                                  |
| Fog Light Front                                                                                                          |  | <div></div> | Rear Bumper Spoiler               | <div></div> |
| <div> Comfort &amp; Convenience</div> |  |                                                                                                |                                   |                                                                                                  |
| Cruise Control                                                                                                           |  | <div></div> | Power Window front - Drivers Side | <div></div> |
| Power Window front - Passenger Side                                                                                      |  | <div></div> | Power Windows Rear                | <div></div> |
| <div> Entertainment</div>             |  |                                                                                                |                                   |                                                                                                  |

|                                                                                                                |                                                                                     |
|----------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                                                                                                                |                                                                                     |
| Bluetooth Player                                                                                               |    |
|  <b>Safety &amp; Security</b> |                                                                                     |
| Airbag Driver Front                                                                                            |    |
| Airbag Passenger Front                                                                                         |  |
| ABS                                                                                                            |    |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

|                 |                                                                                   |
|-----------------|-----------------------------------------------------------------------------------|
| Rear right door |  |
|-----------------|-----------------------------------------------------------------------------------|

### Fenders Condition

|                            |                                                                                   |              |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender                |  | Right Fender |  |
| Condition: Low Visual Dent |                                                                                   |              |                                                                                     |

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|            |                                                                                     |                    |                                                                                       |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|
| Boot Floor |  | Firewall Condition |  |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Head Light Support Condition |  |
|------------------------------|-------------------------------------------------------------------------------------|

### Cowl Top

|          |                                                                                     |
|----------|-------------------------------------------------------------------------------------|
| Cowl Top |  |
|----------|-------------------------------------------------------------------------------------|

### Alloy Wheel/ Rim

|                       |                                                                                     |                      |                                                                                       |
|-----------------------|-------------------------------------------------------------------------------------|----------------------|---------------------------------------------------------------------------------------|
| Left Front Alloy/ Rim |  | Left Rear Alloy/ Rim |  |
|-----------------------|-------------------------------------------------------------------------------------|----------------------|---------------------------------------------------------------------------------------|

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ✓ |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |
| Music System     | ✓ |                      |   |
| Lights           |   |                      |   |
| Headlight        | ✓ | Tail Light Cluster   | ✓ |

Air Conditioning

AC Cooling



AC System Leaks



Rear Left AC Vent



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Steering Wheel



Headliner



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<55%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE