



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 GEELY COOLRAY

GL | 32,406 KM

VIN: LB3762KZ9SX510111

Car highlights



Boosted Engine

This car has a Boosted Engine



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	32406	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	LB3762KZ9SX510111		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Exteriors			
Roof Rails		Running Lights	

Rear Bumper Spoiler	✓	
 Performance		
Hill Descent Control	✓	
 Safety & Security		
Reverse Camera	✓	Airbag Driver Front ✓
Airbag Passenger Front	✓	ABS ✓
 Entertainment		
Bluetooth Player	✓	Apple Play ✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm 

Rear left door



Rear right door

Panel: Paint Chip-off < 5mm 

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Low Visual Dent



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm 

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm 

Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm 

Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top			
Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition			
Light Scuffing < 50mm	!		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys	
Master Key	✓
Dashboard	
Instrument Panel	✓

Controls	✓	Infotainment Display	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓		



Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel Steering Wheel Fair Use Wear	!
Headliner	✓	Toolkit	✓



Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE