



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 NISSAN SUNNY

SV | 102,707 KM

VIN: MDHBN7AD8PG316980

Car highlights

Fuel Efficient

Fuel efficient with 18.0 km/L



Great Parking Assistance

Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	102707	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	18.0 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MDHBN7AD8PG316980		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear			ABS
			
 Comfort & Convenience			
Power Window front - Drivers Side			Power Window front - Passenger Side
			
 Entertainment			

Bluetooth Player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
Panel: Low Visibility Dent < 30mm			

Rear right door			
Panel: Light Scuffing < 50mm			

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Paint Chip-off			

Rear Bumper Condition

Rear Bumper			
Rear Bumper: Light Scuffing < 80mm			

Hood Condition

Hood			
Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm			

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Windshield Condition

Front Windshield		Rear Windshield	
Condition: Driver Side/Stone Chip Mark<5mm			

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition			
------------------------------	---	--	--

Cowl Top

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓		
Lights			
Headlight	✓	Tail Light Cluster	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓

Interiors & Luggage

Dashboard And Instrument Panel		Steering Wheel	
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Color Faded	!
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE