

Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2022 HYUNDAI ACCENT

SMART | 92,503 KM

VIN: MALC741C8NM321564

Car highlights

Cruise control

Cruise control to drive with ease & comfort

Great Parking Assistance

Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable

Bluetooth

Enjoy your drive with bluetooth

Amazing Comfort

Power driver seat

Basic Details

Kilometers	92503	Specs	Yes
Engine	1.6L	Option Type	Basic
Transmission	Automatic	Drive	Front Wheel Drive
Body Type	SEDAN	Fuel Efficiency	16.0 km/L mileage
Wheel Type	Steel Wheels	Exterior Color	Exterior Color White
Interior Trim	Fabric Trim	Number of Airbags	2 Airbags
Seating Capacity	5 Seats	Number of keys	2 Keys
VIN number	MALC741C8NM321564		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

Exteriors			
Fog Light Front	✓		
Comfort & Convenience			
Cruise Control	✓	Power Window front - Drivers Side	✓
Power Window front - Passenger Side	✓	Power Windows Rear	✓
Safety & Security			

Parking Sensors Rear ✓	Airbag Driver Front ✓
Airbag Passenger Front ✓	ABS ✓
Entertainment	
Bluetooth Player ✓	

150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed ✓

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm	!	Rear left door Panel: Colour faded	!
Rear right door Panel: Paint Defect, Colour Mismatch/ Low Brightness	!		

Fenders Condition

Left Fender	✓	Right Fender	✓

Quarter Panels Condition

Left Quarter Panel Condition: Colour faded	!	Right Quarter Panel	✓

Rear Bumper Condition

Rear Bumper Rear Bumper: Scuffing > 80mm, Chip> 8mm	!		

Hood Condition

Hood Bonnet: Paint Damage/ Low Brightness	!		

Running Board Condition

Left Running Board Condition: Repainted, Paint Defect	!	Right Running Board	✓

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement	!	Rear Windshield	✓

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		

Cowl Top

Cowl Top

Rear View Mirror Condition

Left Hand Side Mirror

Right Side Mirror

Alloy Wheel/ Rim

Left Front Alloy/ Rim

Right Front Alloy/ Rim

Right Rear Alloy/ Rim

Monogram

Missing monogram/ logo

Panel Condition

Rear Trunk Panel

Engine & Transmission

Engine

Engine Performance

Engine Oil (Condition & Level)

Exhaust System

Radiator Condition

Radiator Coolant

Transmission Operation

Gear Shifting

Drive Axle

Steering, Suspension & Brakes

Brake System

Parking Brake

Brake Master Cylinder

Suspension

Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key

Central Locking Not Working

Dashboard

Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓

Lights

Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Fog Lights	✓

Air Conditioning

AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Entertainment	✓
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit Jack Availability: Toe Hook Not Available	ⓘ		

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Spare Tyre	✓

Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE