



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 TOYOTA PRADO

GXR | 94,202 KM

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 94202             |  Specs             | Yes                  |
|  Engine           | 4.0L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 9 Airbags            |
|  Seating Capacity | 7 Seats           |  Number of keys    | 1 Keys               |
|  VIN number      | JTEBU3FJ4MK196738 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Cool Box                                                                                                             |  | Power Windows Rear                  |  |
|  <b>Exteriors</b>                 |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  | Roof Rails                          |  |

|                                                                                                                |   |                         |
|----------------------------------------------------------------------------------------------------------------|---|-------------------------|
| Rear Bumper Spoiler                                                                                            | ✓ |                         |
|  <b>Safety &amp; Security</b> |   |                         |
| Navigation                                                                                                     | ✓ | Parking Sensors Front ✓ |
| Parking Sensors Rear                                                                                           | ✓ | Reverse Camera ✓        |
| Airbag Sides                                                                                                   | ✓ | Airbag Curtain Shield ✓ |
| Airbag Knees                                                                                                   | ✓ | Airbag Driver Front ✓   |
| Airbag Passenger Front                                                                                         | ✓ | ABS ✓                   |
|  <b>Performance</b>           |   |                         |
| Hill Descent Control                                                                                           | ✓ | Differential Locks ✓    |
|  <b>Entertainment</b>         |   |                         |
| Bluetooth Player                                                                                               | ✓ |                         |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                              |                                                                                   |                |                                                                                     |
|------------------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door             |  | Rear left door |  |
| Panel: Light Scuffing < 50mm |                                                                                   |                |                                                                                     |

|                              |                                                                                   |  |  |
|------------------------------|-----------------------------------------------------------------------------------|--|--|
| Rear right door              |  |  |  |
| Panel: Light Scuffing < 50mm |                                                                                   |  |  |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                    |                                                                                     |  |  |
|------------------------------------|-------------------------------------------------------------------------------------|--|--|
| Rear Bumper                        |  |  |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |  |  |

### Hood Condition

|      |                                                                                     |  |  |
|------|-------------------------------------------------------------------------------------|--|--|
| Hood |  |  |  |
|------|-------------------------------------------------------------------------------------|--|--|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |  |  |
|----------------|-------------------------------------------------------------------------------------|--|--|
| Sun Roof Glass |  |  |  |
|----------------|-------------------------------------------------------------------------------------|--|--|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|            |                                                                                     |                    |                                                                                       |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|
| Boot Floor |  | Firewall Condition |  |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|

|                              |                                                                                     |  |  |
|------------------------------|-------------------------------------------------------------------------------------|--|--|
| Head Light Support Condition |  |  |  |
|------------------------------|-------------------------------------------------------------------------------------|--|--|

Cowl Top

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ |                    |   |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |
|------------------|---|
| Keys             |   |
| Master Key       | ✓ |
| Dashboard        |   |
| Instrument Panel | ✓ |

|                         |   |                      |   |
|-------------------------|---|----------------------|---|
| Controls                | ✓ | Infotainment Display | ✓ |
| Music System            | ✓ | Camera               | ✓ |
| Lights                  |   |                      |   |
| Headlight               | ✓ | Tail Light Cluster   | ✓ |
| Daylight Running Lights | ✓ |                      |   |
| Air Conditioning        |   |                      |   |
| AC Cooling              | ✓ | AC System Leaks      | ✓ |
| Rear Left AC Vent       | ✓ |                      |   |
| Power/ Manual Windows   | ✓ |                      |   |



## Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |
| Toolkit                        | ✓ |                 |   |



## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <65% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <65% |
| Spare Tyre                 | <75% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE