



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 MAZDA CX 5

GL | 91,801 KM

VIN: JM7KFAWL8P0799928

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	91801	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM7KFAWL8P0799928		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Safety & Security			
Parking Sensors Rear		Reverse Camera	

Airbag Sides	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	Airbag Passenger Front	✓
ABS	✓		
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Light Scuffing < 50mm, Low Visibility
Dent < 30mm



Rear left door



Rear right door



Fenders Condition

Left Fender

Condition: Light Scuffing



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel
Condition: Low Visual Dent, Light Scuffing



Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm



Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Grill Condition	!	
Light Scuffing < 50mm		
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	
Controls	✓	Infotainment Display ✓
Music System	✓	Camera ✓

Lights

Headlight



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted



Steering Wheel

Color Faded



Headliner



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<90%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE