



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 TOYOTA YARIS**

**E | 68,543 KM**

VIN: MR2BF9C39P0009879

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 17.5 km/L



### **Great Parking Assistance**

Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 68543             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 17.5 km/L mileage    |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number       | MR2BF9C39P0009879 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |                                                                                     |                                     |                                                                                       |
|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  Safety & Security     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                      |  | Airbag Curtain Shield               |  |
| Airbag Driver Front                                                                                       |  | Airbag Passenger Front              |  |
| ABS                                                                                                       |  |                                     |                                                                                       |
|  Comfort & Convenience |                                                                                     |                                     |                                                                                       |
| Power Window front - Drivers Side                                                                         |  | Power Window front - Passenger Side |  |

Power Windows Rear



**Entertainment**

Bluetooth Player



Apple Play



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

#### Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door 

#### Rear right door

Panel: Paint Chip-off < 5mm 

### Fenders Condition

Left Fender 

Right Fender 

### Quarter Panels Condition

Left Quarter Panel 

Right Quarter Panel 

### Rear Bumper Condition

#### Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm 

### Hood Condition

#### Hood

Bonnet: Light Scuffing < 50mm 

### Running Board Condition

Left Running Board 

Right Running Board 

### Sunroof Glass Condition (If Equipped)

Sun Roof Glass 

### Windshield Condition

#### Front Windshield

Condition: Driver Side/Stone Chip Mark<5mm 

Rear Windshield 

### Structural Assessment

Chassis Condition 

Apron 

Boot Floor 

Firewall Condition 

|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |

|                  |   |                    |   |
|------------------|---|--------------------|---|
| Music System     | ✓ |                    |   |
| Lights           |   |                    |   |
| Headlight        | ✓ | Tail Light Cluster | ✓ |
| Air Conditioning |   |                    |   |
| AC Cooling       | ✓ | AC System Leaks    | ✓ |

### Interiors & Luggage

|                                                                |   |                              |   |
|----------------------------------------------------------------|---|------------------------------|---|
| Dashboard And Instrument Panel                                 |   | Steering Wheel               |   |
| Dashboard Upholstery: Minor Scuffing/<br>Disfiguration/ Melted | ! | Steering Wheel Fair Use Wear | ! |
| Headliner                                                      | ✓ | Toolkit                      | ✓ |

### Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Life remaining             |      |                           |      |
| LHS Front Tyre             | <75% | LHS Rear Tyre             | <75% |
| RHS Front Tyre             | <65% | RHS Rear Tyre             | <75% |
| Spare Tyre                 | <65% |                           |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE