



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 TOYOTA YARIS

E | 44,693 KM

VIN: MR2BF9C31P0033819

Car highlights



Great condition

Car has low imperfections



Great Parking Assistance

Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	44693	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	17.5 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	MR2BF9C31P0033819		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Airbag Driver Front	
Airbag Passenger Front		ABS	
 Comfort & Convenience			
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
Panel: Low Visibility Dent < 30mm			

Rear right door	
-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Windshield Condition

Front Windshield		Rear Windshield	
------------------	---	-----------------	---

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition	
------------------------------	---

Cowl Top

Cowl Top	
----------	---

Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
-----------------------	---	----------------------	---

Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓
Music System	✓		
Lights			
Headlight	✓	Tail Light Cluster	✓

Air Conditioning

AC Cooling



AC System Leaks



Rear Left AC Vent



Interiors & Luggage

Dashboard And Instrument Panel



Steering Wheel



Headliner



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE