



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 VOLKSWAGEN T ROC

LIFE | 60,586 KM

VIN: WVGAD1A19NV033526

Car highlights



Boosted Engine

This car has a Boosted Engine



Great Parking Assistance

Parking Sensors Front, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	60586	 Specs	Yes
 Engine	1.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WVGAD1A19NV033526		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security					
Parking Sensors Front			Parking Sensors Rear		
Airbag Curtain Shield			Airbag Driver Front		
Airbag Passenger Front			ABS		
 Exteriors					
Running Lights					



Comfort & Convenience

Power Window front -
Drivers Side



Power Window front -
Passenger Side



Power Windows Rear



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
Panel: Light Scuffing < 50mm			

Rear right door	
Panel: Paint Defect	

Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing			

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Windshield Condition

Front Windshield		Rear Windshield	
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm			

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition	
------------------------------	---

Cowl Top			
Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	✓
Rim: Alloy Edge Scuffing			
Grill Condition	!		
Light Scuffing < 50mm			
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key			
Button Faded	!		
Dashboard			

Instrument Panel	✓		
Controls	✓	Infotainment Display	✓
Music System	✓		
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Left AC Vent			
LHS Knob Fair Use Wear	!		

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted, Minor Scuffing/ Crack/ Fair Use Wear	!	Steering Wheel Color Faded	!
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<75%
RHS Front Tyre	<55%	RHS Rear Tyre	<75%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE