



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 SUZUKI CIAZ**

**GLX | 88,930 KM**

VIN: MA3VC7A10PA478904

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 88930             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MA3VC7A10PA478904 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |  |                                                                                     |                                                                                       |
|-----------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  Exteriors             |  |                                                                                     |                                                                                       |
| Fog Light Front                                                                                           |  |  |  |
| Running Lights                                                                                            |  |  |  |
|  Comfort & Convenience |  |                                                                                     |                                                                                       |
| Cruise Control                                                                                            |  |  |  |
| Power Window front - Drivers Side                                                                         |  |  |  |
| Power Window front - Passenger Side                                                                       |  |  |  |
| Power Windows Rear                                                                                        |  |  |  |
|  Safety & Security     |  |                                                                                     |                                                                                       |

|                                                                                                        |   |
|--------------------------------------------------------------------------------------------------------|---|
|                                                                                                        |   |
| Parking Sensors Rear                                                                                   | ✓ |
| Reverse Camera                                                                                         | ✓ |
| Airbag Driver Front                                                                                    | ✓ |
| Airbag Passenger Front                                                                                 | ✓ |
| ABS                                                                                                    | ✓ |
|  <b>Entertainment</b> |   |
| Bluetooth Player                                                                                       | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel  
Condition: Light Scuffing



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



|                        |   |                         |
|------------------------|---|-------------------------|
| Alloy Wheel/ Rim       |   |                         |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim ✓  |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim ✓ |
| Grill Condition        | ! |                         |
| Light Scuffing < 50mm  |   |                         |
| Panel Condition        |   |                         |
| Rear Trunk Panel       | ✓ |                         |

## Engine & Transmission

|                                |   |                      |
|--------------------------------|---|----------------------|
| Engine                         |   |                      |
| Engine Body                    | ✓ | Engine Performance ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System ✓     |
| Radiator Condition             | ✓ | Radiator Coolant ✓   |
| Transmission Operation         |   |                      |
| Gear Shifting                  | ✓ | Drive Axle ✓         |

## Steering, Suspension & Brakes

|                 |   |                         |
|-----------------|---|-------------------------|
| Brake System    |   |                         |
| Parking Brake   | ✓ | Brake Master Cylinder ✓ |
| Brake Fluid     | ✓ |                         |
| Suspension      |   |                         |
| Shock Absorbers | ✓ |                         |

## Electricals, Controls & Lights

|                  |   |                        |
|------------------|---|------------------------|
| Keys             |   |                        |
| Master Key       | ✓ |                        |
| Dashboard        |   |                        |
| Instrument Panel | ✓ |                        |
| Controls         | ✓ | Infotainment Display ✓ |
| Music System     | ✓ | Camera ✓               |

## Lights

Headlight



Tail Light Cluster



Air Conditioning

AC Cooling



AC System Leaks



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/

Disfiguration/ Melted, Minor Scuffing/ Crack/

Fair Use Wear



Steering Wheel

Color Faded



Headliner



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE