



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 GEELY MONJARO

GF+ | 19,168 KM

VIN: LB3KX2S17RS006004

Car highlights



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	19168	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	LB3KX2S17RS006004		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Heads up Display		Climate Control AC	
Cruise Control		Memory Seats	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Ventilated Seat		Power Tailgate/ Power Trunk	
Power Windows Rear			



Safety & Security

Adaptive cruise control



360 degree Camera



Lane Departure Warning System



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Collision Warning System



Front Camera



Side Camera



Airbag Sides



Airbag Curtain Shield



Airbag Driver Front



Airbag Passenger Front



ABS



Exteriors

Roof Rails



Running Lights



Performance

Hill Descent Control



Entertainment

Bluetooth Player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
------------------	---	----------------	---

Rear right door	
Panel: Light Scuffing < 50mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
------	---

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	---

Windshield Condition

Front Windshield		Rear Windshield	
------------------	---	-----------------	---

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition	
------------------------------	---

Cowl Top

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Steering Wheel	✓
Headliner	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE