



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 MAZDA 6

S | 114,072 KM

VIN: JM7GL4S3XP1483074

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 114072            |  Specs             | Yes                  |
|  Engine           | 2.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 14.0 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | JM7GL4S3XP1483074 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Windows Rear                                                                                                   |  |                                     |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Reverse Camera                      |  |

|                                                                                                        |   |                        |   |
|--------------------------------------------------------------------------------------------------------|---|------------------------|---|
| Airbag Sides                                                                                           | ✓ | Airbag Curtain Shield  | ✓ |
| Airbag Driver Front                                                                                    | ✓ | Airbag Passenger Front | ✓ |
| ABS                                                                                                    | ✓ |                        |   |
|  <b>Exteriors</b>     |   |                        |   |
| Running Lights                                                                                         | ✓ |                        |   |
|  <b>Entertainment</b> |   |                        |   |
| Bluetooth Player                                                                                       | ✓ |                        |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door



Rear left door



Rear right door



Panel: Low Visual Dent < 30mm

### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



### Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

### Hood Condition

Hood



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

|                            |   |                       |   |
|----------------------------|---|-----------------------|---|
| Cowl Top                   | ✓ |                       |   |
| Rear View Mirror Condition |   |                       |   |
| Left Hand Side Mirror      | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim           |   |                       |   |
| Left Front Alloy/ Rim      | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim     | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition            | ✓ | Monogram              | ✓ |
| Panel Condition            |   |                       |   |
| Rear Trunk Panel           | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |
|------------------|---|
| Keys             |   |
| Master Key       | ✓ |
| Dashboard        |   |
| Instrument Panel | ✓ |

|                                              |   |                         |   |
|----------------------------------------------|---|-------------------------|---|
| Controls                                     | ✓ | Cruise Control          | ✓ |
| Infotainment Display                         | ✓ | Music System            | ✓ |
| Camera                                       | ✓ |                         |   |
| Lights                                       |   |                         |   |
| Headlight<br>Right: Light Scuff Marks < 50mm | ! | Interior Lights         | ✓ |
| Tail Light Cluster                           | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning                             |   |                         |   |
| AC Cooling                                   | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch                           | ✓ |                         |   |
| Power/ Manual Windows                        | ✓ |                         |   |



## Interiors & Luggage

|                                |   |                                                                 |   |
|--------------------------------|---|-----------------------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                                                 | ✓ |
| Cup Holder                     | ✓ | Steering Wheel                                                  | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery                                                 | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts                                                      | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim<br>Rear Right Door: Crack/ Fair Use Wear | ! |
| Carpet                         | ✓ | Headliner                                                       | ✓ |
| Rear View Mirror               | ✓ | Toolkit                                                         | ✓ |



## Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |

|                |      |               |      |
|----------------|------|---------------|------|
| Life remaining |      |               |      |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre     | <45% |               |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE