



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2022 NISSAN SUNNY**

**SV | 145,239 KM**

VIN: MDHBN7AD4NG155668

## **Car highlights**

### **Fuel Efficient**

Fuel efficient with 18.0 km/L



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 145239            |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 18.0 km/L mileage    |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | MDHBN7AD4NG155668 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |                                                                                     |                                     |                                                                                       |
|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  Safety & Security     |                                                                                     |                                     |                                                                                       |
| Parking Sensors Rear                                                                                      |  | Reverse Camera                      |  |
| Airbag Driver Front                                                                                       |  | Airbag Passenger Front              |  |
| ABS                                                                                                       |  |                                     |                                                                                       |
|  Comfort & Convenience |                                                                                     |                                     |                                                                                       |
| Power Window front - Drivers Side                                                                         |  | Power Window front - Passenger Side |  |



Entertainment

Bluetooth Player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
| Rear right door  |  |                |                                                                                     |

### Fenders Condition

|                            |                                                                                   |              |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender                |  | Right Fender |  |
| Condition: Low Visual Dent |                                                                                   |              |                                                                                     |

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                    |                                                                                     |
|------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |

### Hood Condition

|                                                                     |                                                                                     |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Hood                                                                |                                                                                     |
| Bonnet: Low Visibility Dent < 30mm, Acid Marks/ Bird Dropping < 5mm |  |

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                                    |                                                                                     |                    |                                                                                       |
|------------------------------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|
| Chassis Condition                  |  | Apron              |  |
| Boot Floor                         |  | Firewall Condition |  |
| Condition: Rear End Panel Repaired |                                                                                     |                    |                                                                                       |
| Head Light Support Condition       |  |                    |                                                                                       |

|                            |   |                       |   |
|----------------------------|---|-----------------------|---|
| Cowl Top                   |   |                       |   |
| Cowl Top                   | ✓ |                       |   |
| Rear View Mirror Condition |   |                       |   |
| Left Hand Side Mirror      | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim           |   |                       |   |
| Left Front Alloy/ Rim      | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim     | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition            | ! | Monogram              | ✓ |
| Light Scuffing < 50mm      |   |                       |   |
| Panel Condition            |   |                       |   |
| Rear Trunk Panel           | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |
| Dashboard  |   |

|                                |   |                       |   |
|--------------------------------|---|-----------------------|---|
| Instrument Panel               | ✓ |                       |   |
| Controls                       | ✓ | Infotainment Display  | ✓ |
| Music System                   | ✓ | Camera                | ✓ |
| Lights                         |   |                       |   |
| Headlight                      |   |                       |   |
| Left: Light Scuff Marks < 50mm | ! | Interior Lights       | ✓ |
| Tail Light Cluster             | ✓ |                       |   |
| Air Conditioning               |   |                       |   |
| AC Cooling                     | ✓ | AC System Leaks       | ✓ |
| Parking Sensors                | ✓ | Power/ Manual Windows | ✓ |
| Memory Seats                   | ✓ |                       |   |



## Interiors & Luggage

|                                |   |                                             |   |
|--------------------------------|---|---------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console                             | ✓ |
| Cup Holder                     | ✓ | Steering Wheel                              | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery                             |   |
|                                |   | Driver Seat: Minor Leather/ Fabric Fair Use | ! |
|                                |   | Wear/ Tears, Minor Fair Wear/Fade off       |   |
| Manual Seat Movement           | ✓ | Seat Belts                                  | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim                      | ✓ |
| Carpet                         | ✓ | Headliner                                   | ✓ |
| Rear View Mirror               | ✓ | Toolkit                                     | ✓ |



## Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |

|                |                                                                                  |               |      |
|----------------|----------------------------------------------------------------------------------|---------------|------|
| Spare Tyre     |  |               |      |
| Life remaining |                                                                                  |               |      |
| LHS Front Tyre | <65%                                                                             | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65%                                                                             | RHS Rear Tyre | <65% |
| Spare Tyre     | <75%                                                                             |               |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE