



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 FORD FIGO

AMBIENTE | 59,908 KM

VIN: MAJFKBGZ3KTS58539

Car highlights

Fuel Efficient

Fuel efficient with 17.45 km/L



Bluetooth

Enjoy your drive with bluetooth

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Steering Mounted Audio Controls

Enjoy your drive with steering mounted audio
controls



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	59908	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	Fuel Efficiency	17.45 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MAJFKBGZ3KTS58539		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Power Window front - Drivers Side 	Power Window front - Passenger Side 
 Entertainment	
Bluetooth Player 	
 Safety & Security	

Airbag Curtain Shield		Airbag Passenger Front	
ABS			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off > 5mm 

Rear left door 

Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm 

Fenders Condition

Left Fender

Condition: Light Scuffing 

Right Fender

Right Fender: Paint Chip-off 

Quarter Panels Condition

Left Quarter Panel 

Right Quarter Panel 

Rear Bumper Condition

Rear Bumper 

Hood Condition

Hood 

Running Board Condition

Left Running Board 

Right Running Board 

Windshield Condition

Front Windshield 

Rear Windshield 

Structural Assessment

Chassis Condition 

Apron 

Boot Floor 

Firewall Condition 

Head Light Support Condition 

Cowl Top

Cowl Top 

Fair Use Wear/Crack<5mm		
Rear View Mirror Condition		
Left Hand Side Mirror	✓	Right Side Mirror ✓
Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Monogram	✓	
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	
Dashboard		
Instrument Panel	✓	

Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	!
		Condition: Front Infotainment - Faded Display	
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Left AC Vent	✓		
Power/ Manual Windows	✓		

Interiors & Luggage

Dashboard And Instrument Panel			
Dashboard Upholstery: Scuffing/Crack/ Fair Use Wear	!	Central Console	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE