



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 VOLKSWAGEN TIGUAN

SE | 86,943 KM

VIN: WVGBF2AX9JW974682

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Front, Reverse Camera & more

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	86943	 Specs	Yes
 Engine	1.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	Fuel Efficiency	13.5 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WVGBF2AX9JW974682		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Exteriors			
Fog Light Front		Roof Rails	

Running Lights	✓	
 Safety & Security		
Parking Sensors Front	✓	Parking Sensors Rear ✓
Auto Park Assist	✓	Reverse Camera ✓
Airbag Sides	✓	Airbag Curtain Shield ✓
Airbag Driver Front	✓	Airbag Passenger Front ✓
ABS	✓	
 Entertainment		
Bluetooth Player	✓	Apple Play ✓
Android Auto Play	✓	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Paint Chip-off < 5mm



Rear left door

Panel: Dent



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Light Scuffing



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip

Mark<5mm, Passenger Side/Stone Chip

Mark<8mm



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓		

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



Fog Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Steering Wheel
Color Faded



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE