



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2024 MERCEDES BENZ C 200**

**AMG PREMIUM PLUS | 55,215 KM**

VIN: W1KAF4CB2RR192396

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**

Enjoy your drive with apple play

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Amazing Comfort**

Power driver seat, Memory Seats

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 55215             |  Specs             | Yes                 |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded        |
|  Transmission     | Automatic         |  Drive             | Rear Wheel Drive    |
|  Body Type        | SEDAN             |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 9 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number     | W1KAF4CB2RR192396 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Heads up Display                                                                                                     |  | Climate Control AC                  |  |
| Cruise Control                                                                                                       |  | Memory Seats                        |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Tailgate/ Power Trunk                                                                                          |  | Power Windows Rear                  |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                     |                                                                                       |

|                                                                                                          |   |                          |   |
|----------------------------------------------------------------------------------------------------------|---|--------------------------|---|
| 360 degree Camera                                                                                        | ✓ | Navigation               | ✓ |
| Parking Sensors Front                                                                                    | ✓ | Parking Sensors Rear     | ✓ |
| Auto Park Assist                                                                                         | ✓ | Reverse Camera           | ✓ |
| Blind Spot Monitor                                                                                       | ✓ | Collision Warning System | ✓ |
| Airbag Sides                                                                                             | ✓ | Airbag Curtain Shield    | ✓ |
| Airbag Knees                                                                                             | ✓ | Airbag Driver Front      | ✓ |
| Airbag Passenger Front                                                                                   | ✓ | ABS                      | ✓ |
|  <b>Performance</b>     |   |                          |   |
| Paddle Shift                                                                                             | ✓ |                          |   |
|  <b>Exteriors</b>       |   |                          |   |
| Running Lights                                                                                           | ✓ |                          |   |
|  <b>Entertainment</b> |   |                          |   |
| Bluetooth Player                                                                                         | ✓ | Apple Play               | ✓ |
| Android Auto Play                                                                                        | ✓ |                          |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                  |                                                                                   |                |                                                                                     |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door |  | Rear left door |  |
|------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|

### Rear right door

|                                                     |                                                                                   |
|-----------------------------------------------------|-----------------------------------------------------------------------------------|
| Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm |  |
|-----------------------------------------------------|-----------------------------------------------------------------------------------|

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                              |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                  |  |
| Rear Bumper: Scuffing > 80mm |                                                                                     |

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                  |                                                                                     |                 |                                                                                       |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield |  | Rear Windshield |  |
|------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|            |                                                                                     |                    |                                                                                       |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|
| Boot Floor |  | Firewall Condition |  |
|------------|-------------------------------------------------------------------------------------|--------------------|---------------------------------------------------------------------------------------|

|                              |   |                          |   |
|------------------------------|---|--------------------------|---|
| Head Light Support Condition | ✓ |                          |   |
| Cowl Top                     |   |                          |   |
| Cowl Top                     | ✓ |                          |   |
| Rear View Mirror Condition   |   |                          |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror        | ✓ |
| Alloy Wheel/ Rim             |   |                          |   |
| Left Front Alloy/ Rim        | ! | Left Rear Alloy/ Rim     | ! |
| Rim: Alloy Edge Scuffing     |   | Rim: Alloy Edge Scuffing |   |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim    | ✓ |
| Monogram                     | ✓ |                          |   |
| Panel Condition              |   |                          |   |
| Rear Trunk Panel             | ✓ |                          |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

Keys

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Master Key            | ✓ |                         |   |
| Dashboard             |   |                         |   |
| Instrument Panel      | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | Music System            | ✓ |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch    | ✓ | Rear Left AC Vent       | ✓ |
| Power/ Manual Windows | ✓ | Memory Seats            | ✓ |

## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Cup Holder                     | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Carpet                         | ✓ | Headliner              | ✓ |
| Rear View Mirror               | ✓ | Toolkit                | ✓ |

## Tyres

|                           |   |                          |   |
|---------------------------|---|--------------------------|---|
| Tyres Condition           |   |                          |   |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |

|                            |                                                                                   |                           |                                                                                    |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|------------------------------------------------------------------------------------|
| Right Hand Side Front Tyre |   | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                    |
| Life remaining             |                                                                                   |                           |                                                                                    |
| LHS Front Tyre             | <55%                                                                              | LHS Rear Tyre             | <65%                                                                               |
| RHS Front Tyre             | <55%                                                                              | RHS Rear Tyre             | <55%                                                                               |
| Spare Tyre                 | <55%                                                                              |                           |                                                                                    |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE