



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 HYUNDAI ACCENT

SMART | 56,132 KM

VIN: MALC741C8PM349836

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	56132	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	16.0 km/L mileage
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MALC741C8PM349836		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		Airbag Passenger Front	

ABS		
 Entertainment		
Bluetooth Player		Apple Play 
Android Auto Play		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm		Rear left door	
--	---	----------------	---

Rear right door	
-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Low Visual Dent	
--------------------	---	---	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Roof Condition

Roof	
------	---

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement		Rear Windshield	
--	---	-----------------	---

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor Condition: Rear End Panel Repaired		Firewall Condition	
--	---	--------------------	---

Head Light Support Condition	
------------------------------	---

Cowl Top		
Cowl Top	✓	
Rear View Mirror Condition		
Left Hand Side Mirror	✓	Right Side Mirror ✓
Alloy Wheel/ Rim		
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim ✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim ✓
Grill Condition	!	Monogram ✓
Fully Repainted		
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Coolant	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓

Steering, Suspension & Brakes

Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys	
Master Key	!
Button Faded	

Dashboard			
Instrument Panel			
Malfunction Indication Lights: Engine Warning Light (Check Engine Light)	!		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		
Lights			
Headlight Left: Cracks/ Holes	!	Interior Lights	✓
Tail Light Cluster	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Entertainment	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓

Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			
Life remaining			
LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<55%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE