



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2024 FORD EVEREST

XLS | 44,479 KM

VIN: MNCXW3RN0RAD49806

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	44479	 Specs	Yes
 Engine	2.3L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	7 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	MNCXW3RN0RAD49806		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors				
Fog Light Front			Roof Rails	
Running Lights				
 Comfort & Convenience				
Cruise Control			Power Window front - Drivers Side	
Power Window front - Passenger Side			Power Windows Rear	



Safety & Security

Parking Sensors Rear



Reverse Camera



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



Airbag Passenger Front



ABS



Performance

Hill Descent Control



Differential Locks



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
------------------	---	----------------	---

Rear right door	
Panel: Light Scuffing < 50mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
------	---

Roof Condition

Roof	
------	---

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Windshield Condition

Front Windshield			
Condition: Driver Side/Stone Chip		Rear Windshield	
Mark<5mm, Passenger Side/Stone Chip			
Mark<8mm			

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition	
------------------------------	---

Cowl Top		
Cowl Top	✓	
Rear View Mirror Condition		
Left Hand Side Mirror	✓	Right Side Mirror ✓
Alloy Wheel/ Rim		
Left Rear Alloy/ Rim	✓	Right Front Alloy/ Rim ✓
Right Rear Alloy/ Rim	✓	
Grill Condition	!	Monogram ✓
Light Scuffing < 50mm		
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Turbocharger/ Supercharger	✓	Radiator Condition ✓
Radiator Coolant	✓	
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
4*4 Condition (If Applicable)	✓	

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Fluid	✓	
Suspension		
Shock Absorbers	✓	



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



Fog Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Rear Left AC Vent



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<55%

RHS Rear Tyre

<65%

Spare Tyre

<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE