



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2024 SUZUKI JIMNY

GLX | 38,843 KM

VIN: MA3JC7D23R0171822

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	38843	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	14.5 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	4 Seats	 Number of keys	1 Keys
 VIN number	MA3JC7D23R0171822		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Exteriors			
Fog Light Front			



Safety & Security

Parking Sensors Rear



Reverse Camera



Airbag Sides



Airbag Curtain Shield



Airbag Driver Front



Airbag Passenger Front



ABS



Performance

Hill Descent Control



Entertainment

Bluetooth Player



Apple Play



Android Auto Play



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door

Panel: Dent, Scuffing



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Dent, Scuffing



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Rear Left AC Vent



Rear Entertainment



Power/ Manual Windows



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<73%

LHS Rear Tyre

<73%

RHS Front Tyre

<73%

RHS Rear Tyre

<73%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE