



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2025 GEELY COOLRAY**

**GF | 16,963 KM**

VIN: LB3762KZ3SX511836

## Car highlights



### **Panoramic Roof**

This car has a panoramic roof



### **Adaptive cruise control**

Adaptive cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                    |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|--------------------|
|  Kilometers       | 16963             |  Specs             | Yes                |
|  Engine           | 1.5L              |  Option Type       | Semi Loaded        |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive  |
|  Body Type        | SUV               |  Fuel              | Petrol             |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys             |
|  VIN number     | LB3762KZ3SX511836 |                                                                                                     |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                       |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------|---------------------------------------------------------------------------------------|
| <div> Safety &amp; Security</div> |                                                                                     |                       |                                                                                       |
| Adaptive cruise control                                                                                              |  | 360 degree Camera     |  |
| Lane Departure Warning System                                                                                        |  | Parking Sensors Front |  |
| Parking Sensors Rear                                                                                                 |  | Auto Park Assist      |  |
| Reverse Camera                                                                                                       |  | Blind Spot Monitor    |  |
| Collision Warning System                                                                                             |  | Front Camera          |  |

|                                                                                                                    |   |                                     |   |
|--------------------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Side Camera                                                                                                        | ✓ | Airbag Sides                        | ✓ |
| Airbag Curtain Shield                                                                                              | ✓ | Airbag Driver Front                 | ✓ |
| Airbag Passenger Front                                                                                             | ✓ | ABS                                 | ✓ |
|  <b>Comfort &amp; Convenience</b> |   |                                     |   |
| Climate Control AC                                                                                                 | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                                  | ✓ | Power Window front - Passenger Side | ✓ |
| Power Tailgate/ Power Trunk                                                                                        | ✓ | Power Windows Rear                  | ✓ |
|  <b>Exteriors</b>                 |   |                                     |   |
| Roof Rails                                                                                                         | ✓ | Running Lights                      | ✓ |
| Rear Bumper Spoiler                                                                                                | ✓ |                                     |   |
|  <b>Entertainment</b>           |   |                                     |   |
| Bluetooth Player                                                                                                   | ✓ | Apple Play                          | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                                        |                                                                                   |                                   |                                                                                     |
|----------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------|-------------------------------------------------------------------------------------|
| Front right door                       |  | Rear left door<br>Panel: Scuffing |  |
| Rear right door<br>Panel: Paint Defect |  |                                   |                                                                                     |

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                                                 |                                                                                   |                     |                                                                                     |
|-------------------------------------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel<br>Condition: Paint Chip-off |  | Right Quarter Panel |  |
|-------------------------------------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                   |                                                                                     |
|---------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Light Scuffing < 80mm |  |
|---------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Sunroof Glass Condition (If Equipped)

|                |                                                                                     |
|----------------|-------------------------------------------------------------------------------------|
| Sun Roof Glass |  |
|----------------|-------------------------------------------------------------------------------------|

### Windshield Condition

|                                                                    |                                                                                     |                 |                                                                                       |
|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield<br>Condition: Front Wiper blades need replacement |  | Rear Windshield |  |
|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Boot Floor                   | ✓ | Firewall Condition    | ✓ |
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Rear View Mirror Condition   |   |                       |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Monogram                     | ✓ |                       |   |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |



## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Drive Axle                     | ✓ |                    |   |



## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |



## Electricals, Controls & Lights

|                                 |   |
|---------------------------------|---|
| Keys                            |   |
| Master Key                      | ! |
| Remote/Functions Not Responding |   |

Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



|                |                                                                                  |               |      |
|----------------|----------------------------------------------------------------------------------|---------------|------|
| Spare Tyre     |  |               |      |
| Life remaining |                                                                                  |               |      |
| LHS Front Tyre | <55%                                                                             | LHS Rear Tyre | <65% |
| RHS Front Tyre | <55%                                                                             | RHS Rear Tyre | <65% |
| Spare Tyre     | <55%                                                                             |               |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE