



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 KIA SPORTAGE

GT LINE | 65,013 KM

VIN: U5YPX81B4PL070525

Car highlights



Panoramic Roof

This car has a panoramic roof



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	65013	 Specs	Yes
 Engine	1.6L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	Fuel Efficiency	10.55 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Partial Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	U5YPX81B4PL070525		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Lane Departure Warning System	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Collision Warning System		Airbag Curtain Shield	
Airbag Driver Front		Airbag Passenger Front	

ABS	✓	
 Comfort & Convenience		
Climate Control AC	✓	Cruise Control ✓
Memory Seats	✓	Power Window front - Drivers Side ✓
Power Window front - Passenger Side	✓	Ventilated Seat ✓
Power Tailgate/ Power Trunk	✓	Power Windows Rear ✓
 Exteriors		
Fog Light Front	✓	Roof Rails ✓
Running Lights	✓	Rear Bumper Spoiler ✓
 Performance		
Paddle Shift	✓	Hill Descent Control ✓
Differential Locks	✓	
 Entertainment		
Bluetooth Player	✓	Apple Play ✓
Android Auto Play	✓	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Paint Chip-off < 5mm



Rear left door



Rear right door

Panel: Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Light Scuffing



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor	⚠	Firewall Condition	✓
Condition: Rear End Panel Repaired			
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		

Electricals, Controls & Lights

Keys			
------	--	--	--

Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel Steering Wheel Fair Use Wear	!
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

 Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<85%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE