



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 HYUNDAI PALISADE

SMART | 29,417 KM

VIN: KMHR381C3SU843137

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	29417	 Specs	Yes
 Engine	3.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	8 Seats	 Number of keys	1 Keys
 VIN number	KMHR381C3SU843137		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Power Window front - Drivers Side		Power Window front - Passenger Side	
Power Windows Rear			
 Safety & Security			
Parking Sensors Rear		Reverse Camera	

Blind Spot Monitor	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
 Exteriors			
Roof Rails	✓	Running Lights	✓
 Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Monogram



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

 Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre





A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE