



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 KIA TELLURIDE

EX | 50,785 KM

VIN: 5XXP381C8PG336811

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

## Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 50785             |  Specs             | Yes                 |
|  Engine           | 3.8L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | All Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 6 Airbags           |
|  Seating Capacity | 7 Seats           |  Number of keys    | 1 Keys              |
|  VIN number       | 5XXP381C8PG336811 |                                                                                                     |                     |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                     |                                                                                       |
| Climate Control AC                                                                                                   |  | Cruise Control                      |  |
| Power Window front - Drivers Side                                                                                    |  | Power Window front - Passenger Side |  |
| Power Tailgate/ Power Trunk                                                                                          |  | Power Windows Rear                  |  |
|  <b>Exteriors</b>                 |                                                                                     |                                     |                                                                                       |
| Fog Light Front                                                                                                      |  | Roof Rails                          |  |

|                                                                                                                |   |                        |   |
|----------------------------------------------------------------------------------------------------------------|---|------------------------|---|
| Running Lights                                                                                                 | ✓ | Rear Bumper Spoiler    | ✓ |
|  <b>Safety &amp; Security</b> |   |                        |   |
| Parking Sensors Rear                                                                                           | ✓ | Reverse Camera         | ✓ |
| Airbag Sides                                                                                                   | ✓ | Airbag Curtain Shield  | ✓ |
| Airbag Driver Front                                                                                            | ✓ | Airbag Passenger Front | ✓ |
| ABS                                                                                                            | ✓ |                        |   |
|  <b>Performance</b>           |   |                        |   |
| Hill Descent Control                                                                                           | ✓ |                        |   |
|  <b>Entertainment</b>         |   |                        |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play             | ✓ |
| Android Auto Play                                                                                              | ✓ |                        |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Boot Floor



Head Light Support Condition



Cowl Top

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ! |                       |   |
| Fully Repainted        |   |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |
| Music System     | ✓ | Camera               | ✓ |

## Lights

Headlight



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



Power/ Manual Windows



Memory Seats



## Interiors & Luggage

Dashboard And Instrument Panel



Steering Wheel



Headliner



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre





## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE