



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 TOYOTA COROLLA CROSS**

**XL | 82,982 KM**

VIN: RKLKUBAG4N0501570

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 82982             |  Specs             | Yes                  |
|  Engine           | 1.8L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number     | RCLKUBAG4N0501570 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                   |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                                       |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                                  |  | Power Windows Rear                |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                   |                                                                                       |
| Parking Sensors Rear                                                                                                 |  | Airbag Driver Front               |  |
| Airbag Passenger Front                                                                                               |  | ABS                               |  |



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Paint Defect



Rear left door



Rear right door

Panel: Light Scuffing < 50mm



### Fenders Condition

Left Fender

Condition: Low Visual Dent, Light Scuffing



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Light Scuffing



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



|                            |   |                       |   |
|----------------------------|---|-----------------------|---|
| Cowl Top                   |   |                       |   |
| Cowl Top                   | ✓ |                       |   |
| Rear View Mirror Condition |   |                       |   |
| Left Hand Side Mirror      | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim           |   |                       |   |
| Left Front Alloy/ Rim      | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim     | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition            | ✓ | Monogram              | ✓ |
| Panel Condition            |   |                       |   |
| Rear Trunk Panel           | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |  |  |
|------------|---|--|--|
| Keys       |   |  |  |
| Master Key | ✓ |  |  |
| Dashboard  |   |  |  |

|                      |   |                       |   |
|----------------------|---|-----------------------|---|
| Instrument Panel     | ✓ |                       |   |
| Controls             | ✓ | Cruise Control        | ✓ |
| Infotainment Display | ✓ | Music System          | ✓ |
| Lights               |   |                       |   |
| Headlight            | ✓ | Interior Lights       | ✓ |
| Tail Light Cluster   | ✓ |                       |   |
| Air Conditioning     |   |                       |   |
| AC Cooling           | ✓ | AC System Leaks       | ✓ |
| Rear Blower Switch   | ✓ |                       |   |
| Parking Sensors      | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

|                                                             |   |                                     |   |
|-------------------------------------------------------------|---|-------------------------------------|---|
| Dashboard And Instrument Panel                              |   | Central Console                     |   |
| Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted | ! | Gear Shift Knob: Knob Fair Use Wear | ! |
| Cup Holder                                                  | ✓ | Steering Wheel                      | ! |
|                                                             |   | Color Faded                         |   |
| Sunvisor                                                    | ✓ | Seat Upholstery                     | ✓ |
| Manual Seat Movement                                        | ✓ | Seat Belts                          | ✓ |
| Head Rest                                                   | ✓ | Door Controls And Trim              | ✓ |
| Carpet                                                      | ✓ | Headliner                           | ✓ |
| Rear View Mirror                                            | ✓ | Toolkit                             | ✓ |

## Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |

|                |      |               |      |
|----------------|------|---------------|------|
| Life remaining |      |               |      |
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre     | <65% |               |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE