



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 MG GT

COMFORT | 80,810 KM

VIN: 97148420519714842

Car highlights



Great condition

Car has low imperfections



Sunroof

This car has a sunroof

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	80810	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	97148420519714842		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience		
Sunroof		Memory Seats
		
 Safety & Security		
Reverse Camera		
 Entertainment		
Infotainment System		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Boot Floor



Head Light Support Condition



Cowl Top

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Turbocharger/ Supercharger	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓		
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE