



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 HYUNDAI GRAND I10

SMART PLUS | 65,649 KM

VIN: MALB251C0SM552616

Car highlights



Great condition

Car has low imperfections



Music System

Enjoy your drive with music system

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	65649	 Specs	Yes
 Engine	1.2L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Partial Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	MALB251C0SM552616		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Memory Seats	
 Safety & Security	
Reverse Camera	
 Entertainment	
Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

 Exterior

Doors condition			
Front right door		Rear left door	
Rear right door			
Fenders Condition			
Left Fender		Right Fender	
Quarter Panels Condition			
Left Quarter Panel		Right Quarter Panel	
Rear Bumper Condition			
Rear Bumper			
Hood Condition			
Hood			
Roof Condition			
Roof			
Running Board Condition			
Left Running Board		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Boot Floor	
Head Light Support Condition			
Cowl Top			

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Turbocharger/ Supercharger	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓		
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE