



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2022 MAZDA CX 30

ELITE | 53,668 KM

VIN: JM7DMAW72N0204716

## Car highlights



### Great condition

Car has low imperfections



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                    |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|--------------------|
|  Kilometers       | 53668             |  Specs             | Yes                |
|  Engine           | 2.0L              |  Option Type       | Semi Loaded        |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive  |
|  Body Type        | SUV               |  Fuel              | Petrol             |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Red |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 6 Airbags          |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys             |
|  VIN number     | JM7DMAW72N0204716 |                                                                                                     |                    |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |  |                                                                                     |                                 |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|--|-------------------------------------------------------------------------------------|---------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |  |                                                                                     |                                 |                                                                                       |
| Sunroof                                                                                                              |  |  | Steering Mounted Audio Controls |  |
|  <b>Safety &amp; Security</b>     |  |                                                                                     |                                 |                                                                                       |
| Parking Sensors Rear                                                                                                 |  |  | Reverse Camera                  |  |
|  <b>Entertainment</b>             |  |                                                                                     |                                 |                                                                                       |

Infotainment System



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                                                |                                                                                     |                     |                                                                                       |
|------------------------------------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Doors condition                                |                                                                                     |                     |                                                                                       |
| Front right door                               |    | Rear left door      |    |
| Rear right door                                |    |                     |                                                                                       |
| Fenders Condition                              |                                                                                     |                     |                                                                                       |
| Left Fender                                    |    | Right Fender        |    |
| Quarter Panels Condition                       |                                                                                     |                     |                                                                                       |
| Left Quarter Panel                             |    | Right Quarter Panel |    |
| Rear Bumper Condition                          |                                                                                     |                     |                                                                                       |
| Rear Bumper                                    |  |                     |                                                                                       |
| Hood Condition                                 |                                                                                     |                     |                                                                                       |
| Hood                                           |  |                     |                                                                                       |
| Roof Condition                                 |                                                                                     |                     |                                                                                       |
| Roof                                           |  |                     |                                                                                       |
| Running Board Condition                        |                                                                                     |                     |                                                                                       |
| Left Running Board                             |  | Right Running Board |  |
| Sunroof Glass Condition (If Equipped)          |                                                                                     |                     |                                                                                       |
| Sun Roof Glass                                 |  |                     |                                                                                       |
| Windshield Condition                           |                                                                                     |                     |                                                                                       |
| Front Windshield                               |                                                                                     |                     |                                                                                       |
| Condition: Front Wiper blades need replacement |  | Rear Windshield     |  |
| Structural Assessment                          |                                                                                     |                     |                                                                                       |
| Chassis Condition                              |  | Apron               |  |
| Boot Floor                                     |  | Firewall Condition  |  |

|                              |   |                       |   |
|------------------------------|---|-----------------------|---|
| Head Light Support Condition | ✓ |                       |   |
| Cowl Top                     |   |                       |   |
| Cowl Top                     | ✓ |                       |   |
| Rear View Mirror Condition   |   |                       |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim             |   |                       |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim | ✓ |
| Monogram                     | ✓ |                       |   |
| Panel Condition              |   |                       |   |
| Rear Trunk Panel             | ✓ |                       |   |

## **Engine & Transmission**

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Transmission Operation         |   |                    |   |
| Drive Axle                     | ✓ |                    |   |

## **Steering, Suspension & Brakes**

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## **Electricals, Controls & Lights**

|                          |   |
|--------------------------|---|
| Keys                     |   |
| Master Key               | ! |
| Manual Key Not Available |   |
| Dashboard                |   |

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Instrument Panel      | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | Music System            | ✓ |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch    | ✓ | Rear Left AC Vent       | ✓ |
| Power/ Manual Windows | ✓ |                         |   |



## Interiors & Luggage

|                                                                |   |                        |   |
|----------------------------------------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel                                 |   |                        |   |
| Dashboard Upholstery: Minor Scuffing/<br>Disfiguration/ Melted | ! | Central Console        | ✓ |
| Cup Holder                                                     | ✓ | Steering Wheel         | ✓ |
| Sunvisor                                                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement                                           | ✓ | Seat Belts             | ✓ |
| Head Rest                                                      | ✓ | Door Controls And Trim | ✓ |
| Carpet                                                         | ✓ | Headliner              | ✓ |
| Rear View Mirror                                               | ✓ | Toolkit                | ✓ |



## Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |

|                |                                                                                  |               |      |
|----------------|----------------------------------------------------------------------------------|---------------|------|
| Spare Tyre     |  |               |      |
| Life remaining |                                                                                  |               |      |
| LHS Front Tyre | <55%                                                                             | LHS Rear Tyre | <55% |
| RHS Front Tyre | <55%                                                                             | RHS Rear Tyre | <55% |
| Spare Tyre     | <45%                                                                             |               |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE