



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2023 MITSUBISHI ATTRAGE**

**GLX HIGHLINE | 77,380 KM**

VIN: MMDAFT6J4PH002562

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Music System**

Enjoy your drive with music system



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 77380             |  Specs             | Yes                   |
|  Engine           | 1.2L              |  Option Type       | Fully Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 20.2 km/L mileage     |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Silver |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags             |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys                |
|  VIN number      | MMDAFT6J4PH002562 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                           |                                                                                     |                                   |                                                                                       |
|-----------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------|---------------------------------------------------------------------------------------|
|  Exteriors             |                                                                                     |                                   |                                                                                       |
| Fog Light Front                                                                                           |  |                                   |                                                                                       |
|  Comfort & Convenience |                                                                                     |                                   |                                                                                       |
| Cruise Control                                                                                            |  | Power Window front - Drivers Side |  |
| Power Window front - Passenger Side                                                                       |  | Power Windows Rear                |  |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

 **Exterior**

|                                       |                                                                                     |                     |                                                                                       |
|---------------------------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Doors condition                       |                                                                                     |                     |                                                                                       |
| Front right door                      |    | Rear left door      |    |
| Rear right door                       |    |                     |                                                                                       |
| Fenders Condition                     |                                                                                     |                     |                                                                                       |
| Left Fender                           |    | Right Fender        |    |
| Quarter Panels Condition              |                                                                                     |                     |                                                                                       |
| Left Quarter Panel                    |    | Right Quarter Panel |    |
| Rear Bumper Condition                 |                                                                                     |                     |                                                                                       |
| Rear Bumper                           |  |                     |                                                                                       |
| Hood Condition                        |                                                                                     |                     |                                                                                       |
| Hood                                  |  |                     |                                                                                       |
| Roof Condition                        |                                                                                     |                     |                                                                                       |
| Roof                                  |  |                     |                                                                                       |
| Running Board Condition               |                                                                                     |                     |                                                                                       |
| Left Running Board                    |  | Right Running Board |  |
| Sunroof Glass Condition (If Equipped) |                                                                                     |                     |                                                                                       |
| Sun Roof Glass                        |  |                     |                                                                                       |
| Windshield Condition                  |                                                                                     |                     |                                                                                       |
| Front Windshield                      |  | Rear Windshield     |  |
| Structural Assessment                 |                                                                                     |                     |                                                                                       |
| Chassis Condition                     |  | Boot Floor          |  |
| Head Light Support Condition          |  |                     |                                                                                       |
| Cowl Top                              |                                                                                     |                     |                                                                                       |

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ✓ |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                            |   |
|--------------------------------|---|----------------------------|---|
| Engine                         |   |                            |   |
| Engine Body                    | ✓ | Engine Performance         | ✓ |
| Engine Oil (Condition & Level) | ✓ | Turbocharger/ Supercharger | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant           | ✓ |
| Transmission Operation         |   |                            |   |
| Gear Shifting                  | ✓ | Drive Axle                 | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Music System            | ✓ | Camera             | ✓ |
| Lights                  |   |                    |   |
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ |                    |   |
| Power/ Manual Windows   | ✓ | Memory Seats       | ✓ |

### Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |

### Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE