



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 MITSUBISHI ATTRAGE

GLX HIGHLINE | 89,570 KM

VIN: MMDAFT6J7PH001714

## Car highlights

### Fuel Efficient

Fuel efficient with 20.2 km/L



### Cruise control

Cruise control to drive with ease & comfort

### Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K  
applicable



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 89570             |  Specs             | Yes                 |
|  Engine           | 1.2L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SEDAN             | Fuel Efficiency                                                                                     | 20.2 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys              |
|  VIN number      | MMDAFT6J7PH001714 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                          |  |                                                                                                |                                   |                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|-----------------------------------|--------------------------------------------------------------------------------------------------|
| <div> Exteriors</div>                 |  |                                                                                                |                                   |                                                                                                  |
| Fog Light Front                                                                                                          |  | <div></div> | Rear Bumper Spoiler               | <div></div> |
| <div> Comfort &amp; Convenience</div> |  |                                                                                                |                                   |                                                                                                  |
| Cruise Control                                                                                                           |  | <div></div> | Power Window front - Drivers Side | <div></div> |
| Power Window front - Passenger Side                                                                                      |  | <div></div> | Power Windows Rear                | <div></div> |
| <div> Entertainment</div>             |  |                                                                                                |                                   |                                                                                                  |

|                                                                                                                |                                                                                                                                                                                              |
|----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                                                                                                                |                                                                                                                                                                                              |
| Bluetooth Player                                                                                               |                                                                                                              |
|  <b>Safety &amp; Security</b> |                                                                                                                                                                                              |
| Airbag Driver Front                                                                                            |  Airbag Passenger Front  |
| ABS                                                                                                            |                                                                                                             |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                                                  |                                                                                   |                |                                                                                     |
|--------------------------------------------------|-----------------------------------------------------------------------------------|----------------|-------------------------------------------------------------------------------------|
| Front right door<br>Panel: Light Scuffing < 50mm |  | Rear left door |  |
| Rear right door<br>Panel: Light Scuffing < 50mm  |  |                |                                                                                     |

### Fenders Condition

|                                          |                                                                                   |                                                                               |                                                                                     |
|------------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender<br>Right Fender: Dent, Paint Chip-off, Fender liner minor damage |  |
|------------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                                                                        |                                                                                     |
|----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper<br>Rear Bumper: Dent < 50mm, Scuffing > 80mm, Chip< 8mm, Crack/ Misaligned |  |
|----------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Hood Condition

|                                                 |                                                                                     |
|-------------------------------------------------|-------------------------------------------------------------------------------------|
| Hood<br>Bonnet: Acid Marks/ Bird Dropping < 5mm |  |
|-------------------------------------------------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Running Board Condition

|                    |                                                                                     |                     |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Left Running Board |  | Right Running Board |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|

### Windshield Condition

|                                                                    |                                                                                     |                 |                                                                                       |
|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|
| Front Windshield<br>Condition: Front Wiper blades need replacement |  | Rear Windshield |  |
|--------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------|

### Structural Assessment

|                   |                                                                                     |       |                                                                                       |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|
| Chassis Condition |  | Apron |  |
|-------------------|-------------------------------------------------------------------------------------|-------|---------------------------------------------------------------------------------------|

|                              |   |                        |   |
|------------------------------|---|------------------------|---|
| Boot Floor                   | ✓ | Firewall Condition     | ✓ |
| Head Light Support Condition | ! |                        |   |
| Poor Refurb Job              |   |                        |   |
| Cowl Top                     |   |                        |   |
| Cowl Top                     | ✓ |                        |   |
| Rear View Mirror Condition   |   |                        |   |
| Left Hand Side Mirror        | ✓ | Right Side Mirror      | ✓ |
| Alloy Wheel/ Rim             |   |                        |   |
| Left Rear Alloy/ Rim         | ✓ | Right Front Alloy/ Rim | ✓ |
| Right Rear Alloy/ Rim        | ✓ |                        |   |
| Grill Condition              | ! | Monogram               | ✓ |
| Broken/ Fair Use Wear        |   |                        |   |
| Panel Condition              |   |                        |   |
| Rear Trunk Panel             | ✓ |                        |   |

## Engine & Transmission

|                        |   |                                |   |
|------------------------|---|--------------------------------|---|
| Engine                 |   |                                |   |
| Engine Performance     | ✓ | Engine Oil (Condition & Level) | ✓ |
| Exhaust System         | ✓ | Radiator Condition             | ✓ |
| Radiator Coolant       | ✓ |                                |   |
| Transmission Operation |   |                                |   |
| Gear Shifting          | ✓ | Drive Axle                     | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

## Keys

Master Key

Remote/Boot Not Opening



## Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure

Warning Light



Controls



Cruise Control



Infotainment Display



Music System

Condition: Knob Fair Use Wear



## Lights

Headlight



Interior Lights



Tail Light Cluster



Fog Lights



Air Conditioning

AC Cooling



AC System Leaks



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/

Disfiguration/ Melted



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



## Tyres

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Tyres Condition            |                                                                                   |                           |                                                                                     |
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <75%                                                                              | LHS Rear Tyre             | <40%                                                                                |
| RHS Front Tyre             | <75%                                                                              | RHS Rear Tyre             | <45%                                                                                |
| Spare Tyre                 | <65%                                                                              |                           |                                                                                     |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE