



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 GAC GS8

GT | 82,031 KM

VIN: LMGJS1G83M1157404

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	82031	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	LMGJS1G83M1157404		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Front Camera		Side Camera	
Airbag Sides		Airbag Curtain Shield	
Airbag Driver Front		Airbag Passenger Front	

ABS	✓	
 Comfort & Convenience		
Climate Control AC	✓	Cruise Control ✓
Memory Seats	✓	Power Window front - Drivers Side ✓
Power Window front - Passenger Side	✓	Ventilated Seat ✓
Power Windows Rear	✓	
 Performance		
Paddle Shift	✓	
 Exteriors		
Roof Rails	✓	Running Lights ✓
Rear Bumper Spoiler	✓	
 Entertainment		
Bluetooth Player	✓	Apple Play ✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door		Rear left door	
------------------	---	----------------	---

Rear right door

Panel: Paint Defect, Colour Mismatch/ Low Brightness	
--	---

Fenders Condition

Left Fender		Right Fender	
Condition: Low Visual Dent			

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	--	---------------------	--

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Crack/ Misaligned	

Hood Condition

Hood	
------	---

Roof Condition

Roof	
Roof Moulding Condition: Colour fade	

Running Board Condition

Left Running Board		Right Running Board	
--------------------	---	---------------------	---

Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	---

Windshield Condition

Front Windshield		Rear Windshield	
Condition: Front Wiper blades need replacement		Wiper blade damaged	

Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	!		
Fair Use Wear/Crack>5mm			
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Monogram	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	!		

Remote/Functions Not Responding

Dashboard

Instrument Panel



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight

Left: Low Brightness lamps



Interior Lights



Tail Light Cluster



Daylight Running Lights



Fog Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Rear Left AC Vent



Power/ Manual Windows



Seat Heaters



Memory Seats



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<90%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE