



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 NISSAN X TRAIL

S | 31,683 KM

VIN: JN8AT3MT3PW005397

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	31683	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JN8AT3MT3PW005397		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Performance			
Paddle Shift			
 Safety & Security			

Parking Sensors Rear	✓	Reverse Camera	✓
Front Camera	✓	Airbag Sides	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
Airbag Passenger Front	✓	ABS	✓
 Exteriors			
Running Lights	✓		
 Entertainment			
Bluetooth Player	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front right door

Panel: Low Visibility Dent < 30mm, Acid Marks/ Bird Dropping > 5mm, Paint Chip-off > 5mm



Rear left door

Panel: Scuffing, Colour faded



Rear right door

Panel: Low Visual Dent < 30mm, Colour Mismatch/ Low Brightness



Fenders Condition

Left Fender

Condition: Paint Chip-off, Light Scuffing, Low Visual Dent



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Acid Marks/ Bird Dropping



Right Quarter Panel

Condition: Low Visual Dent, Scuffing/ Scratch



Rear Bumper Condition

Rear Bumper

Rear Bumper: Chip> 8mm, Dent > 50mm



Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping > 5mm



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement



Rear Windshield

Wiper blade damaged



Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Rear Alloy/ Rim	✓	Right Front Alloy/ Rim	✓
Right Rear Alloy/ Rim	✓		
Grill Condition			
Scuffing > 50mm	!	Monogram	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Performance	✓	Engine Oil (Condition & Level)	✓
Exhaust System	✓	Turbocharger/ Supercharger	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key

Remote/Boot Not Opening



Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure

Warning Light



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight

Left: Scuff Marks > 50mm



Interior Lights



Tail Light Cluster



Daylight Running Lights



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/
Disfiguration/ Melted



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE