



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2025 GEELY OKAVANGO**

**GK | 2,922 KM**

VIN: L6TVX1S62SY001603

### **Car highlights**



#### **Great condition**

Car has low imperfections



#### **Cruise control**

Cruise control to drive with ease & comfort

#### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



#### **Apple play**

Enjoy your drive with apple play



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                     |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|---------------------|
|  Kilometers       | 2922              |  Specs             | Yes                 |
|  Engine           | 2.0L              |  Option Type       | Semi Loaded         |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SUV               |  Fuel              | Petrol              |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Grey |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 4 Airbags           |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | L6TVX1S62SY001603 |                                                                                                     |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                      |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|----------------------|---------------------------------------------------------------------------------------|
|  <b>Safety &amp; Security</b>     |                                                                                     |                      |                                                                                       |
| 360 degree Camera                                                                                                    |  | Parking Sensors Rear |  |
| Reverse Camera                                                                                                       |  | Blind Spot Monitor   |  |
| Airbag Sides                                                                                                         |  | Airbag Driver Front  |  |
| Airbag Passenger Front                                                                                               |  | ABS                  |  |
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                      |                                                                                       |

|                                                                                                        |   |                                     |   |
|--------------------------------------------------------------------------------------------------------|---|-------------------------------------|---|
| Climate Control AC                                                                                     | ✓ | Cruise Control                      | ✓ |
| Power Window front - Drivers Side                                                                      | ✓ | Power Window front - Passenger Side | ✓ |
| Power Windows Rear                                                                                     | ✓ |                                     |   |
|  <b>Exteriors</b>     |   |                                     |   |
| Roof Rails                                                                                             | ✓ | Running Lights                      | ✓ |
|  <b>Performance</b>   |   |                                     |   |
| Hill Descent Control                                                                                   | ✓ |                                     |   |
|  <b>Entertainment</b> |   |                                     |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play                          | ✓ |
| Android Auto Play                                                                                      | ✓ |                                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Sunroof Glass Condition (If Equipped)

Sun Roof Glass



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Right Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Monogram



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Transmission Operation

Gear Shifting



Drive Axle



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Keys                 |   |                         |   |
| Master Key           | ✓ |                         |   |
| Dashboard            |   |                         |   |
| Instrument Panel     | ✓ |                         |   |
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | Music System            | ✓ |
| Camera               | ✓ |                         |   |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC System Leaks         | ✓ |
| Rear Blower Switch   | ✓ | Rear Left AC Vent       | ✓ |
| Rear Entertainment   | ✓ | Power/ Manual Windows   | ✓ |
| Memory Seats         | ✓ |                         |   |

## Interiors & Luggage

|                                |   |                        |   |
|--------------------------------|---|------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console        | ✓ |
| Cup Holder                     | ✓ | Steering Wheel         | ✓ |
| Sunvisor                       | ✓ | Seat Upholstery        | ✓ |
| Manual Seat Movement           | ✓ | Seat Belts             | ✓ |
| Head Rest                      | ✓ | Door Controls And Trim | ✓ |
| Carpet                         | ✓ | Headliner              | ✓ |
| Rear View Mirror               | ✓ | Toolkit                | ✓ |

---

 **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre





## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE