



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2025 HYUNDAI ELANTRA

SMART | 47,898 KM

VIN: KMHLN41B1SU847817

Car highlights



Great condition

Car has low imperfections



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	47898	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	16.0 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	KMHLN41B1SU847817		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors				
Fog Light Front			Running Lights	
 Comfort & Convenience				
Cruise Control			Power Window front - Drivers Side	
Power Window front - Passenger Side			Power Windows Rear	
 Safety & Security				

Parking Sensors Rear		Airbag Driver Front	
Airbag Passenger Front		ABS	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition			
Front right door		Rear left door	
Rear right door			
Fenders Condition			
Left Fender		Right Fender	
Quarter Panels Condition			
Left Quarter Panel		Right Quarter Panel	
Rear Bumper Condition			
Rear Bumper			
Hood Condition			
Hood			
Roof Condition			
Roof			
Running Board Condition			
Left Running Board		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Boot Floor	
Head Light Support Condition			
Cowl Top			

Cowl Top	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Turbocharger/ Supercharger	✓
Radiator Condition	✓	Radiator Coolant	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓		
Dashboard			
Instrument Panel	✓		
Controls	✓	Infotainment Display	✓

Music System	✓	Camera	✓
Lights			
Headlight	✓	Tail Light Cluster	✓
Daylight Running Lights	✓		
Air Conditioning			
AC Cooling	✓		
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Steering Wheel	✓	Headliner	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE