



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

12 Months Warranty

This car comes with 12 months or 20,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 JEEP WRANGLER

UNLIMITED RUBICON | 29,539 KM

VIN: 1C4HJXFN4PW632695

Car highlights



Low Mileage

This car has been driven less than 15,000 km
a year



Adaptive cruise control

Adaptive cruise control to drive with ease &
comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	29539	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	1 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1C4HJXFN4PW632695		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Navigation	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Collision Warning System	
Airbag Sides		Airbag Driver Front	
Airbag Passenger Front		ABS	



Comfort & Convenience

Climate Control AC



Cruise Control



Power Window front -
Drivers Side



Power Window front -
Passenger Side



Power Windows Rear



Exteriors

Fog Light Front



Running Lights



Performance

Hill Descent Control



Differential Locks



Entertainment

Bluetooth Player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door Panel: Light Scuffing < 50mm		Rear left door	
--	---	----------------	---

Rear right door	
-----------------	---

Fenders Condition

Left Fender Condition: Light Scuffing		Right Fender	
--	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Rear Bumper Condition

Rear Bumper
Rear Bumper: Light Scuffing < 80mm, Dent <  50mm

Hood Condition

Hood
Bonnet: Light Scuffing < 50mm 

Roof Condition

Roof 

Running Board Condition

Left Running Board Condition: Fair Use Wear		Right Running Board Condition: Light Scuffing < 80mm	
--	---	---	---

Windshield Condition

Front Windshield Condition: Front Wiper blades need replacement		Rear Windshield Wiper blade damaged	
--	---	--	---

Structural Assessment

Chassis Condition		Apron	
-------------------	---	-------	---

Boot Floor		Firewall Condition	
------------	---	--------------------	---

Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Fluid	✓		
Suspension			

Shock Absorbers	✓		
-----------------	---	--	--

Electricals, Controls & Lights			
---	--	--	--

Dashboard			
Instrument Panel	✓		
Cruise Control	✓	Infotainment Display	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC System Leaks	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Power/ Manual Windows	✓
Seat Heaters	✓		

Interiors & Luggage			
--	--	--	--

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Steering Wheel	✓
Sunvisor	✓	Seat Upholstery	✓
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	
		Jack Availability: Warning Triangle Not Available	!

 Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<95%

LHS Rear Tyre

<95%

RHS Front Tyre

<95%

RHS Rear Tyre

<95%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE