



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 NISSAN KICKS**

**SV | 89,017 KM**

VIN: 3N1CP5C94NL465250

### **Car highlights**



#### **Cruise control**

Cruise control to drive with ease & comfort



#### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear & more



#### **Android Auto**

Enjoy your drive with Android Auto



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 89017             |  Specs             | Yes                  |
|  Engine           | 1.6L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 16.7 km/L mileage    |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | 3N1CP5C94NL465250 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                          |  |                                                                                                |                                   |                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|-----------------------------------|--------------------------------------------------------------------------------------------------|
| <div> Exteriors</div>                 |  |                                                                                                |                                   |                                                                                                  |
| Fog Light Front                                                                                                          |  | <div></div> | Roof Rails                        | <div></div> |
| <div> Comfort &amp; Convenience</div> |  |                                                                                                |                                   |                                                                                                  |
| Cruise Control                                                                                                           |  | <div></div> | Power Window front - Drivers Side | <div></div> |
| Power Window front - Passenger Side                                                                                      |  | <div></div> | Power Windows Rear                | <div></div> |
| <div> Safety &amp; Security</div>     |  |                                                                                                |                                   |                                                                                                  |

|                                                                                                        |   |                     |   |
|--------------------------------------------------------------------------------------------------------|---|---------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera      | ✓ |
| Blind Spot Monitor                                                                                     | ✓ | Airbag Driver Front | ✓ |
| Airbag Passenger Front                                                                                 | ✓ | ABS                 | ✓ |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player                                                                                       | ✓ | Android Auto Play   | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front right door

Panel: Light Scuffing < 50mm



Rear left door



Rear right door



### Fenders Condition

Left Fender



Right Fender



### Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel  
Condition: Chip



### Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



### Hood Condition

Hood

Bonnet: Light Scuffing < 50mm



### Roof Condition

Roof



### Running Board Condition

Left Running Board



Right Running Board



### Windshield Condition

Front Windshield



Rear Windshield



### Structural Assessment

Chassis Condition



Apron



Boot Floor



Firewall Condition



Head Light Support Condition



Cowl Top

|                            |   |                       |   |
|----------------------------|---|-----------------------|---|
| Cowl Top                   | ✓ |                       |   |
| Rear View Mirror Condition |   |                       |   |
| Left Hand Side Mirror      | ✓ | Right Side Mirror     | ✓ |
| Alloy Wheel/ Rim           |   |                       |   |
| Left Front Alloy/ Rim      | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim     | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition            | ! | Monogram              | ✓ |
| Light Scuffing < 50mm      |   |                       |   |
| Panel Condition            |   |                       |   |
| Rear Trunk Panel           | ✓ |                       |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Brake Fluid     | ✓ |                       |   |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|            |   |
|------------|---|
| Keys       |   |
| Master Key | ✓ |
| Dashboard  |   |

|                       |   |                 |   |
|-----------------------|---|-----------------|---|
| Instrument Panel      | ✓ |                 |   |
| Controls              | ✓ | Cruise Control  | ✓ |
| Infotainment Display  | ✓ | Music System    | ✓ |
| Camera                | ✓ |                 |   |
| Lights                |   |                 |   |
| Headlight             | ✓ | Interior Lights | ✓ |
| Tail Light Cluster    | ✓ | Fog Lights      | ✓ |
| Air Conditioning      |   |                 |   |
| AC Cooling            | ✓ | AC System Leaks | ✓ |
| Power/ Manual Windows | ✓ |                 |   |



## Interiors & Luggage

|                                |   |                                                        |   |
|--------------------------------|---|--------------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console<br>Gear Shift Knob: Knob Fair Use Wear | ! |
| Steering Wheel                 | ✓ | Sunvisor                                               | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement                                   | ✓ |
| Seat Belts                     | ✓ | Head Rest                                              | ✓ |
| Door Controls And Trim         | ✓ | Carpet<br>Front Left Floor Mat: Smudge/Burn/Crack      | ! |
| Headliner                      | ✓ | Rear View Mirror                                       | ✓ |
| Toolkit                        | ✓ |                                                        |   |



## Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |

|                |      |               |      |
|----------------|------|---------------|------|
| Life remaining |      |               |      |
| LHS Front Tyre | <75% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <75% |
| Spare Tyre     | <65% |               |      |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE