



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 KIA K5

LX | 91,861 KM

VIN: KNAG24173P5226734

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Reverse Camera, Parking Sensors Rear



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	91861	 Specs	Yes
 Engine	2.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	11.7 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KNAG24173P5226734		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Power Window front - Drivers Side	
Power Window front - Passenger Side		Power Windows Rear	
 Safety & Security			
Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		Airbag Passenger Front	

ABS	✓	
 Exteriors		
Running Lights	✓	
 Entertainment		
Bluetooth Player	✓	Apple Play ✓
Android Auto Play	✓	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front right door

Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm 

Rear left door

Panel: Dent 

Rear right door

Panel: Low Visual Dent < 30mm, Scuffing > 50mm 

Fenders Condition

Left Fender

Condition: Low Visual Dent, Light Scuffing 

Right Fender

Right Fender: Paint Chip-off 

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent 

Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm, Dent < 50mm, Colour Mismatch/ Low Brightness 

Hood Condition

Hood

Bonnet: Paint Damage/ Low Brightness, Acid Marks/ Bird Dropping > 5mm 

Roof Condition

Roof



Running Board Condition

Left Running Board



Right Running Board



Windshield Condition

Front Windshield

Condition: Front Wiper blades need replacement 

Rear Windshield



Structural Assessment

Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	!		
Fair Use Wear/Crack>5mm			
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Right Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Right Front Alloy/ Rim	!
Rim: Alloy Edge Scuffing		Rim: Alloy Edge Scuffing	
Right Rear Alloy/ Rim	!		
Rim: Alloy Edge/Scuffing			
Grill Condition	!	Monogram	✓
Fully Repainted			
Panel Condition			
Rear Trunk Panel			
Dent	!		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Coolant	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓

Steering, Suspension & Brakes

Brake System

Parking Brake	✓	Brake Master Cylinder	✓
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Dashboard

Instrument Panel

Malfunction Indication Lights: Tire Pressure
Warning Light



Controls



Cruise Control



Infotainment Display



Music System



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights
Right DRL: Low Brightness



Air Conditioning

AC Cooling



AC System Leaks



Rear Blower Switch



Rear Left AC Vent



Power/ Manual Windows



Front Left: Master Switch Buttons Faded



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Carpet



Front Left Floor Mat: Smudge/Burn/Crack

Headliner



Rear View Mirror



Toolkit

Jack Availability: Warning Triangle Not Available



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<45%

LHS Rear Tyre

<55%

RHS Front Tyre

<45%

RHS Rear Tyre

<55%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE