



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



COMING SOON



2023 BESTUNE T99

DELUXE | 36,001 KM

VIN: 97148427509714842

### Car highlights



#### **Great condition**

Car has low imperfections



#### **Panoramic Roof**

This car has a panoramic roof



#### **Music System**

Enjoy your drive with music system



#### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 36001             |  Specs             | Yes                  |
|  Engine           | 2.0L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 4 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | 97148427509714842 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                                                                                       |
| Panoramic Sunroof                                                                                                    |  | Memory Seats                                                                          |
|                                                                                                                      |                                                                                     |  |
|  <b>Safety &amp; Security</b>     |                                                                                     |                                                                                       |
| Reverse Camera                                                                                                       |  |                                                                                       |
|  <b>Entertainment</b>             |                                                                                     |                                                                                       |
| Infotainment System                                                                                                  |  |                                                                                       |



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

|                                       |                                                                                     |                     |                                                                                       |
|---------------------------------------|-------------------------------------------------------------------------------------|---------------------|---------------------------------------------------------------------------------------|
| Doors condition                       |                                                                                     |                     |                                                                                       |
| Front right door                      |    | Rear left door      |    |
| Rear right door                       |    |                     |                                                                                       |
| Fenders Condition                     |                                                                                     |                     |                                                                                       |
| Left Fender                           |    | Right Fender        |    |
| Quarter Panels Condition              |                                                                                     |                     |                                                                                       |
| Left Quarter Panel                    |    | Right Quarter Panel |    |
| Rear Bumper Condition                 |                                                                                     |                     |                                                                                       |
| Rear Bumper                           |  |                     |                                                                                       |
| Hood Condition                        |                                                                                     |                     |                                                                                       |
| Hood                                  |  |                     |                                                                                       |
| Roof Condition                        |                                                                                     |                     |                                                                                       |
| Roof                                  |  |                     |                                                                                       |
| Running Board Condition               |                                                                                     |                     |                                                                                       |
| Left Running Board                    |  | Right Running Board |  |
| Sunroof Glass Condition (If Equipped) |                                                                                     |                     |                                                                                       |
| Sun Roof Glass                        |  |                     |                                                                                       |
| Windshield Condition                  |                                                                                     |                     |                                                                                       |
| Front Windshield                      |  | Rear Windshield     |  |
| Structural Assessment                 |                                                                                     |                     |                                                                                       |
| Chassis Condition                     |  | Boot Floor          |  |
| Head Light Support Condition          |  |                     |                                                                                       |
| Cowl Top                              |                                                                                     |                     |                                                                                       |

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Cowl Top               | ✓ |                       |   |
| Alloy Wheel/ Rim       |   |                       |   |
| Left Front Alloy/ Rim  | ✓ | Left Rear Alloy/ Rim  | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Grill Condition        | ✓ |                       |   |
| Panel Condition        |   |                       |   |
| Rear Trunk Panel       | ✓ |                       |   |

## Engine & Transmission

|                                |   |                            |   |
|--------------------------------|---|----------------------------|---|
| Engine                         |   |                            |   |
| Engine Body                    | ✓ | Engine Performance         | ✓ |
| Engine Oil (Condition & Level) | ✓ | Turbocharger/ Supercharger | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant           | ✓ |
| Transmission Operation         |   |                            |   |
| Gear Shifting                  | ✓ | Drive Axle                 | ✓ |

## Steering, Suspension & Brakes

|                 |   |                       |   |
|-----------------|---|-----------------------|---|
| Steering        |   |                       |   |
| Steering wheel  | ✓ |                       |   |
| Brake System    |   |                       |   |
| Parking Brake   | ✓ | Brake Master Cylinder | ✓ |
| Suspension      |   |                       |   |
| Shock Absorbers | ✓ |                       |   |

## Electricals, Controls & Lights

|                  |   |                      |   |
|------------------|---|----------------------|---|
| Keys             |   |                      |   |
| Master Key       | ✓ |                      |   |
| Dashboard        |   |                      |   |
| Instrument Panel | ✓ |                      |   |
| Controls         | ✓ | Infotainment Display | ✓ |

|                         |   |                    |   |
|-------------------------|---|--------------------|---|
| Music System            | ✓ | Camera             | ✓ |
| Lights                  |   |                    |   |
| Headlight               | ✓ | Tail Light Cluster | ✓ |
| Daylight Running Lights | ✓ |                    |   |
| Air Conditioning        |   |                    |   |
| AC Cooling              | ✓ |                    |   |
| Power/ Manual Windows   | ✓ | Memory Seats       | ✓ |

### Interiors & Luggage

|                                |   |                 |   |
|--------------------------------|---|-----------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Steering Wheel                 | ✓ | Headliner       | ✓ |

### Tyres

|                            |   |                           |   |
|----------------------------|---|---------------------------|---|
| Tyres Condition            |   |                           |   |
| Left Hand Side Front Tyre  | ✓ | Left Hand Side Rear Tyre  | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre                 | ✓ |                           |   |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE