



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 JEEP CHEROKEE LIMITED | 126,754 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



| Exteriors Exteriors | | | |
|-----------------------|----------|----------------------|----------|
| Fog Light Front | ~ | Roof Rails | ✓ |
| Running Lights | ✓ | Rear Bumper Spoiler | ~ |
| Halogen Headlights | ✓ | | |
| Safety & Security | | | |
| Navigation | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera | ✓ | Traction Control | ~ |
| Airbag Curtain Shield | ✓ | Airbag Knees | ~ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ~ |
| √a Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



| Roof | ✓ | | |
|--|----------|--|----------|
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ~ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm | (!) | Rear Windshield | • |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ~ |
| Head Light Support Condition | ✓ | | |
| Cowl Top Cowl Top Fair Use Wear/Crack<5mm | ! | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm | (!) |

| Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! | Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm | (!) |
|--|-------------|---|----------|
| Spare Alloy/ Rim Condition | | Min. Alloy Face, Coun & Contin | |
| Sparo / time of tallion | | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | (!) | Monogram | ✓ |
| Light Scuffing < 50mm | | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |
| | | | |
| Engine & Transmission | | | |
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| 4*4 Condition (If Applicable) | ✓ | Transmission Fluid | ✓ |
| © Ctearing Comments of Dark | | | |
| Steering, Suspension & Brakes | | | |
| Steering | | | |
| Steering wheel | > | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ~ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| | | | |

| Pedals | ✓ | | |
|---|----------|----------------------------|----------|
| Suspension | | | |
| Shock Absorbers | ✓ | | |
| Electricals, Controls & Lights | | | |
| Keys | | | |
| Master Key | ✓ | Spare Key(s) Fair Use Wear | ! |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Navigation System | ✓ |
| Music System | ✓ | | |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Camera | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster Left Tail Lamp: Crack / Fair Use Wear < 5mm, Light Scuffing < 50mm | ! | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | • |

| AC System Leaks | ✓ | Center AC Vent | ✓ |
|---|----------|--|----------|
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger Extensive Wear Of Strip | ! | USB Charging Port | ✓ |
| Power/ Manual Windows | ~ | Seat Heaters | ✓ |
| Interiors & Luggage | | | |
| Dashboard And Instrument Panel | ✓ | Central Console Gear Shift Knob: Knob Fair Use Wear | (!) |
| Cup Holder | ✓ | Glove Box | • |
| Steering Wheel Steering Wheel Fair Use Wear | (!) | Sunvisor | • |
| Seat Upholstery Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off | (!) | Manual Seat Movement | • |
| Seat Belts | ✓ | Head Rest | • |
| Door Controls And Trim | ✓ | Grab Handle | • |
| Carpet | ✓ | Headliner Rear Left: Smudge/Disfiguration | (!) |
| Rear View Mirror | ~ | Toolkit | ✓ |
| Tyres | | | |
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Life remaining | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <65% |

Spare Tyre <65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE