



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 LAND ROVER RANGE ROVER EVOQUE

DYNAMIC | 76,348 KM

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 76348 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | All Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 12 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | SALVA2BG3EH866625 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Power Tailgate/ Power Trunk |  |
| Rear Defogger |  | Central Armrest |  |
| Automatic Headlights |  | | |



Exteriors

Fog Light Front



Running Lights



Rear Bumper Spoiler



LED Headlights



Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Auto Park Assist



Reverse Camera



Blind Spot Monitor



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Paddle Shift



Hill Descent Control



Entertainment

Bluetooth Player



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior



Doors condition

| | | | |
|---|---|--|---|
| Front left door |  | Front right door Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm |  |
| Rear left door Panel: Scratch < 50mm |  | Rear right door Panel: Paint Chip-off < 5mm |  |

Fenders Condition

| | | | |
|--|---|--|---|
| Left Fender Condition: Paint Chip-off < 5mm, Scratch < 50mm |  | Right Fender Right Fender: Scratch < 50mm |  |
|--|---|--|---|


Quarter Panels Condition

| | | | |
|--------------------|---|--|---|
| Left Quarter Panel |  | Right Quarter Panel Condition: Scratch < 50mm, Paint Chip-off < 5mm |  |
|--------------------|---|--|---|

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|--|---|
| Rear Bumper Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |
|--|---|

Hood Condition

| | |
|---|---|
| Hood Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|---|---|

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Pillars Condition

| | | | |
|--|---|---|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board Condition: Light Scuffing < 80mm | ! |
| Windshield Condition | | | |
| Front Windshield Condition: Driver Side/Stone Chip Mark<5mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! | Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! |
| Right Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! | Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition Light Scuffing < 50mm | ! | Monogram Paint Chip-off < 5mm | ! |

| | | | |
|------------------|---|-------|---|
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Gear shift | ✓ |
| Drive Axle | ✓ | Transmission Fluid | ✓ |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |

Electricals, Controls & Lights

| | | | |
|------|--|--|--|
| Keys | | | |
|------|--|--|--|

| | | | |
|----------------------|---|-------------------------|---|
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Radar (If Equipped) | ✓ |
| Navigation System | ✓ | Music System | ✓ |
| Sunroof Operation | | | |
| Sunroof | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

| | | | |
|---|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | | | |
| Driver Seat: Minor Fair Wear/Fade off, Minor Smudge/ Cracks | ! | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Carpet | ✓ |
| Headliner | ✓ | Rear View Mirror | ✓ |
| Toolkit | ✓ | | |

Tyres

| | | | |
|---------------------------|------|--------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Rear Tyre | ✓ | Spare Tyre | ✓ |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <55% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <65% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE