



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2015 VOLKSWAGEN JETTA

TRENDLINE | 146,364 KM

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Great Parking Assistance

Parking Sensors Front, Parking Sensors Rear



### Music System

Enjoy your drive with music system



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>146364</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Brown</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>WVWRV1AJ2FM211367</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Steering Column Adjuster	
 <b>Safety &amp; Security</b>			
Parking Sensors Front		Parking Sensors Rear	
Traction Control		Airbag Curtain Shield	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Exteriors</b>			
Halogen Headlights			
 <b>Entertainment</b>			
Infotainment System		USB player	

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Paint Chip-



off < 5mm, Light Scuffing < 50mm

Fenders Condition

Left Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm

Right Fender

Right Fender: Dent < 30mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Scuffing > 80mm, Chip < 8mm, Light Scuffing < 80mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar	!	Right A Pillar	✓
Inner Condition: Fair Use Wear			
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Antenna	!	Grill Condition	!
Bent/Broken/Fair Use Wear/Missing		Scuffing > 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		

## Engine & Transmission

### Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

### Battery

Battery Terminal & Tightness 

### Fuel System

Fuel Tank 

### Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

## Steering, Suspension & Brakes

### Steering

Steering wheel 

### Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Pedals 

### Suspension

Shock Absorbers 

## Electricals, Controls & Lights

### Keys

Master Key  Spare Key(s) 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel	!	
Dash Light Operation: Not Working		
Airbags		
Airbags	✓	
Controls		
Fuel Door Release: Loose/ Tight Opening/ Closing	!	Cruise Control
		✓
Infotainment Display	✓	Engine Sensors
		✓
		Music System
OBD Connector	✓	Steering Mounted Audio Controls: Button(s) Faded
		!
Lights		
Headlight	✓	Interior Lights
		✓
Tail Light Cluster	✓	License Plate Light
		✓
Air Conditioning		
AC Cooling	✓	AC Switch
		✓
AC System Leaks	✓	Center AC Vent
		✓
Front Right AC Vent	✓	Heater
		Heater Not Working
		!
Rear Blower Switch	!	
Knob Restricted Movement		
Parking Sensors	✓	Rear Defogger
		✓
USB Charging Port	✓	Power/ Manual Windows
		✓

## **Interiors & Luggage**

Dashboard And Instrument Panel	✓	Central Console	!
		Gear Shift Knob: Knob Fair Use Wear	
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery			
Driver Seat: Minor Smudge/ Cracks, Minor Leather/ Fabric Fair Use Wear/ Tears	!	Manual Seat Movement	✓

Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre			
Crack/ Uneven Wear			

### Life remaining

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE