



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 6 Months Warranty

This car comes with 6 months or 10,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 TOYOTA COROLLA**

**XLI | 20,547 KM**

VIN: RKLBB0BE3N0043298

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

 Kilometers	20547	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	RKLBB0BE3N0043298		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Steering Column Adjuster			
 <b>Safety &amp; Security</b>			
Parking Sensors Rear		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 <b>Entertainment</b>			
Bluetooth Player		Apple Play	
Android Auto Play		Infotainment System	
USB player			
 <b>Exteriors</b>			
Halogen Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Chip< 8mm	

Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon


Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Battery

Battery Terminal & Tightness



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	!	Center AC Vent	✓
Temp In Running < 14°C			
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		



## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Cigarette Lighter: Cigarette Lighter Missing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓



Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
---------------------------	---	--------------------------	---

Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
----------------------------	---	---------------------------	---

Spare Tyre	✓		
------------	---	--	--

Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<75%
----------------	------	---------------	------

RHS Front Tyre	<65%	RHS Rear Tyre	<75%
----------------	------	---------------	------

Spare Tyre	<75%		
------------	------	--	--



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE