



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 VOLKSWAGEN GOLF

GTI | 72,171 KM

VIN: WVWFK2AU3GW326383

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Apple play
















Enjoy your drive with apple play



Amazing Comfort

Power driver seat




Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 72171 |  Specs | Yes |
|  Engine | 2.0L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | HATCHBACK |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 7 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WVWFK2AU3GW326383 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Rear Defogger |  |
| Central Armrest |  | Steering Column Adjuster |  |
|  Exteriors | | | |

| | | | |
|--|---|----------------------|---|
| Fog Light Front | ✓ | Running Lights | ✓ |
| Rear Bumper Spoiler | ✓ | Halogen Headlights | ✓ |
|  Performance | | | |
| Paddle Shift | ✓ | | |
|  Safety & Security | | | |
| Parking Sensors Front | ✓ | Parking Sensors Rear | ✓ |
| Auto Park Assist | ✓ | Traction Control | ✓ |
| Airbag Curtain Shield | ✓ | Airbag Knees | ✓ |
| Airbag Driver Front | ✓ | ABS | ✓ |
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Apple Play | ✓ |
| Android Auto Play | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender

Condition: Paint Chip-off < 5mm, Light Scuffing < 50 mm



Right Fender

Condition: Low Visual Dent < 30mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Chip<5mm, Light Scuffing<50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



| | | | |
|--|---|--|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield Condition: Passenger Side/Light Scuffing<50mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Antenna | ✓ | Grill Condition Light Scuffing < 50mm | ! |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)

Remote Functions Not Responding



| | | | |
|----------------------|---|-------------------------|---|
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | Engine Sensors | ✓ |
| OBD Connector | ✓ | Music System | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | Fog Lights | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |



Interiors & Luggage

| | | | |
|--|---|-----------------|---|
| Dashboard And Instrument Panel | | | |
| Dashboard And Instrument Panel: Light Scuffing/Crack | ! | Central Console | ✓ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |

| | | | |
|---|---|---|---|
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim Front Left Door: Light Scuffing | ! | Grab Handle | ✓ |
| Carpet | ✓ | Headliner Front Left: Light Smudge/Disfiguration | ! |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|---|---------------------------|---|
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |

Tyres Depth (Remaining)

| | | | |
|----------------|------|---------------|------|
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <65% | RHS Rear Tyre | <75% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE