



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 KIA CERATO

LX | 149,127 KM

VIN: KNAFJ4117G5467416

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort
















Power driver seat



Airbag safety









Airbag Driver Front







Basic Details

| | | | |
|--|-------------------|---|--------------------|
|  Kilometers | 149127 |  Specs | Yes |
|  Engine | 1.6L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Fabric Trim |  Number of Airbags | 1 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | KNAFJ4117G5467416 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|--|---|---|
|  Comfort & Convenience | | | |
| Rear Defogger | |  | Central Armrest |
| | | |  |
|  Entertainment | | | |
| Bluetooth Player | |  | Infotainment System |
| | | |  |
| USB player | |  | |
| | | | |
|  Exteriors | | | |

| | | |
|--|---|--|
| Halogen Headlights |  | |
|  Safety & Security | | |
| Airbag Driver Front |  | ABS  |
| Central Locking |  | Child Safety Locking  |

150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door

Handle: Scratch < 50mm, Paint Chip-off < 5mm 

Front right door

Handle: Paint Chip-off < 5mm 

Rear left door

Panel: Dent < 30mm, Scratch < 50mm 

Rear right door

Inner Frame: minor imperfection 

Fenders Condition

Left Fender




Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Paint Chip-off < 5mm 

Right Quarter Panel

Condition: Light Scuffing<50mm 

Front Bumper Condition

Front Bumper




Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm 

Trunk Condition

Trunk

Door Trim: Fair Use Wear 

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

| | | | |
|--|---|---|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board Condition: Light Scuffing < 80mm | ! |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor Condition: Refurbished to RTA standards, Poor Refurb Job | ! |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror Body: Paint Faded | ! | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | Right Hand Side Mirror | ✓ |
| Alloy Wheel/ Rim | | | |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel Arch | ✓ | Wheel cover Front Right: Edge/ Scuffs < 80mm | ! |
| Grill Condition Light Scuffing < 50mm | ! | Monogram | ✓ |
| Window Glass | ✓ | Wiper | ! |

Operation: minor imperfection

Panel Condition

Rear Trunk Panel
minor imperfection



Engine & Transmission

Engine

Engine Body

Mount Condition: minor imperfection



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle

Rear Axle: minor imperfection



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers

Front Left Link Rod: minor imperfection



Electricals, Controls & Lights

Keys

| | | | |
|------------------------------------|---|--------------------------------|---|
| Master Key | ✓ | Spare Key(s) | ✓ |
| Door Locks | | | |
| Child Safety Locking | ✓ | | |
| Dashboard | | | |
| Instrument Panel | ✓ | | |
| Airbags | | | |
| Airbags | ✓ | | |
| Controls | ✓ | Infotainment Display | ✓ |
| Engine Sensors | ✓ | OBD Connector | ✓ |
| Music System | ! | | |
| Condition: Button(s) Faded | | | |
| Lights | | | |
| Headlight | ! | Interior Lights | ✓ |
| Left: Light Scuff Marks < 50mm | | | |
| Tail Light Cluster | ! | Turn Signal Lights | ✓ |
| Left Tail Lamp: minor imperfection | | | |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ! | Center AC Vent | ✓ |
| Temp In Running < 14°C | | | |
| Front Right AC Vent | ✓ | Heater | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ! |
| | | Front Left: minor imperfection | |

Interiors & Luggage

| | | | |
|--------------------------------|---|---------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console | ! |
| | | Box: Minor Color Low Brightness | |
| Glove Box | ✓ | Steering Wheel | ✓ |
| Sunvisor | ✓ | Seat Upholstery | ✓ |

| | | | |
|---------------------------------|---|--|---|
| Manual Seat Movement | ✓ | Seat Belts | ✓ |
| Head Rest | ✓ | Door Controls And Trim | ! |
| | | Front Left Door: Light Scuffing/ Disfiguration | |
| Grab Handle | ✓ | Carpet | ! |
| | | Front Right Floor Mat: Smudge/Burn/Crack | |
| Headliner | ! | Rear View Mirror | ✓ |
| Rear Left: Smudge/Disfiguration | | | |
| Toolkit | ✓ | | |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <65% | LHS Rear Tyre | <75% |
| RHS Front Tyre | <75% | RHS Rear Tyre | <65% |
| Spare Tyre | <55% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE