



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2018 MITSUBISHI ATTRAGE**

**GLX MID | 91,874 KM**

VIN: MMDAF26J4JH001946

### **Car highlights**



#### **Great Parking Assistance**

Parking Sensors Rear



#### **Music System**

Enjoy your drive with music system



#### **Steering Mounted Audio Controls**

Enjoy your drive with steering mounted audio controls



#### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>91874</b>	 Specs	<b>Yes</b>
 Engine	<b>1.2L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MMDAF26J4JH001946</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>	
Fog Light Front	
 <b>Safety &amp; Security</b>	
Parking Sensors Rear	
Airbag Driver Front	
Central Locking	
Traction Control	
ABS	
Child Safety Locking	



## Comfort & Convenience

Steering Mounted Audio Controls		Rear Defogger	
Steering Column Adjuster			



## Entertainment

Infotainment System		
---------------------	--	--

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm



Rear left door



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Dent < 30mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Dent < 50mm, Chip < 8mm, Crack/ Misaligned



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm



Trunk Condition

Trunk



Trunk condition

Trunk



## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Light Scuffing < 50mm

Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



## Windshield Condition

Front Windshield

Condition: Passenger Side/Light

Scuffing<50mm, Driver Side/Stone Chip



Mark<5mm, Passenger Side/Stone Chip

Rear Windshield



Mark<8mm

Light Scuffing < 50mm

## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim



Left Rear Alloy/ Rim



Left Front Alloy/ Rim



Right Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Front Right: Face/ Scuffs < 50mm

Antenna



Grill Condition



Broken/ Fair Use Wear

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Button Faded

Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System

Audio Inputs: Not Working



Lights

Headlight



Right: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Power/ Manual Windows



## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Glove Box		Steering Wheel Color Faded	
Sunvisor		Seat Upholstery Driver Seat: Minor Fair Wear/Fade off	
Manual Seat Movement Driver Seat: Seat Rail Rusting		Seat Belts	
Head Rest		Door Controls And Trim Front Left Door: Light Scuffing	
Grab Handle		Carpet	
Headliner Rear Left: Smudge/Disfiguration		Rear View Mirror	
Toolkit			

## **Tyres**

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<65%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE